

FACILITY CONDITION ASSESSMENT

DLR Group 1650 Spruce Street, Suite 300 Riverside, California 92507 **Kevin Fleming**



JUNIPER ELEMENTARY SCHOOL

1809 South Juniper Street Escondido, California 92025

PREPARED BY:

EMG | A Bureau Veritas Company 10461 Mill Run Circle, Suite 1100 Owings Mills, Maryland 21117 800.733.0660 www.emgcorp.com

EMG CONTACT:

Mark Surdam Program Manager 800.733.0660 x6251 msurdam@emgcorp.com

EMG PROJECT #:

136488.19R000-011.354

DATE OF REPORT:

July 18, 2019

ON SITE DATE:

June 27, 2019





TABLE OF CONTENTS

1.	Executive Summary	
	Campus Overview and Assessment Details	
	Buildings	
	Significant/Systemic Findings and Deficiencies	
	Facility Condition Index (FCI)	
	Key Findings	
	Plan Types	
2.	Building 41-44	
3.	Building A	. 1
4.	Building B	. 1
5.	Building C	. 1
6.	Building D	
7.	Building E	
8.	Building F	
9.	Building G	
-	Portables	
	Site Summary	
	ADA Accessibility	
	Purpose and Scope	
	Opinions of Probable Costs	
17.	Methodology	
	Definitions	
15	Certification	
	Appendices	
10.	Appendices	. ა

1. Executive Summary

Campus Overview and Assessment Details

General Information	
Main Address	1809 South Juniper Street, Escondido, California 92025
Site Developed	1959 Limited Renovated 2000
Property Type	Elementary School
Current Occupants	Escondido USD
Building Area	55,066 SF
Number of Buildings	Nine
Date(s) of Visit	June 27, 2019
Management Point of Contact	Escondido Union School District Francis Spoonemore, Director, Maintenance and Operations 760-432-2421 Ext. 211 fspoonemore@eusd.org
On-site Point of Contact (POC)	Mr. Kevin Fleming
Assessment and Report Prepared By	Nezar M. Tibi
Reviewed By	Alex Israel, Technical Report Reviewer for Mark Surdam Program Manager msurdam@emgcorp.com 800.733.0660 x6251

Buildings

Building Summary							
Building	Use	Constructed	Area(SF)				
41-44	Classrooms	1959 / 2000	2,500				
A	Administration	1959 / 2000	6,200				
В	MPR and Kitchen	1959 / 2000	6,600				
С	Classrooms	1959 / 2000	6,600				
D	Classrooms	1959 / 2000	6,600				

Building Summary							
Building	Use	Constructed	Area(SF)				
Е	Classrooms	1959 / 2000	6,200				
F	Classrooms	1959 / 2000	3,300				
G	Classrooms	1959 / 2000	3,300				
Portable	Classrooms and restrooms	2000 / 2016	18,800				

Unit Allocation

All of the property is occupied by the Escondido Union School District programs. There are no tenants leasing buildings or rooms at the school.

Areas Observed

The interior spaces were observed in order to gain a clear understanding of the property's overall condition. Other areas accessed included the site within the property boundaries, the exterior of the property, and the roofs.

Key Spaces Not Observed

All key areas of the property were accessible and observed.

Significant/Systemic Findings and Deficiencies

Historical Summary

The elementary school campus was originally constructed in 1959. Portables buildings were added in 2000, and a restroom building was added in 2016. The facility has been used as an elementary school since it was originally constructed.

Architectural

The buildings consist of wood-framed construction on concrete slabs. The exteriors consist of painted stucco with wood windows, main entry doors, and service doors. Roofs are primarily gabled and finished with asphalt shingles. The portables exteriors consist of wood siding with metal windows and main entry doors. Portables roofs are primarily flat and finished with metal and single-ply PVC membranes. A new restroom building was added in 2016 adjacent to the west portables. The interior finishes have been well maintained throughout the facilities. Finishes have been replaced as needed and are anticipated for lifecycle replacement based on normal wear.

Mechanical, Electrical, Plumbing and Fire (MEPF)

The MEPF systems and infrastructure vary significantly in age; while some components were being replaced during the site visit, many remain older, with some still original to the construction dates of each building. The equipment consist of rooftop package units and split systems for the permanent buildings and wall-mounted heat pumps for the portables. The mechanical infrastructure is generally in fair working condition. The electrical infrastructure is original. Plumbing and fire protection systems and equipment are anticipated for lifecycle replacement. All MEPF equipment is anticipated for lifecycle replacement.

Site

Site improvements and landscaping are generally in fair condition and appear to have been well maintained. The concrete sidewalks have significant areas of cracking and uneven pavement throughout the campus. The asphalt pavement appears to have been maintained with seal coating and striping with some areas of significant cracking in the parking lot. Pavement seal and stripe is anticipated.

Recommended Additional Studies

The storm water drainage system throughout the school campus has been problematic. A professional civil engineer must be retained to analyze the existing condition, provide recommendations and, if necessary, estimate the scope and cost of any required repairs. The cost of this study is included in the cost tables. Due to the ambiguity of the required repair scope at the time of this assessment, the cost for any possible subsequent repairs is not included.

Facility Condition Index (FCI)

One of the major goals of the FCA is to calculate each building's Facility Condition Index (FCI), which provides a theoretical objective indication of a building's overall condition. By definition, the FCI is defined as the ratio of the cost of current needs divided by current replacement value (CRV) of the facility. The chart below presents the industry standard ranges and cutoff points.

FCI Ranges and Description					
0 – 5% In new or well-maintained condition, with little or no visual evidence of wear or other defic					
5 – 10%	Subjected to wear but is still in a serviceable and functioning condition.				
10 – 30%	Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life.				
30% and above	Has reached the end of its useful or serviceable life. Renewal is now necessary.				

The deficiencies and lifecycle needs identified in this assessment provide the basis for a portfolio-wide capital improvement funding strategy. In addition to the current FCI, extended FCIs have been developed to provide owners the intelligence needed to plan and budget for the "keep-up costs" for their facilities. As such the 3-year, 5-year, and 10-year FCIs are calculated by dividing the anticipated needs of those respective time periods by current replacement value. As a final point, the FCIs ultimately provide more value when used to relatively compare facilities across a portfolio instead of being overanalyzed and scrutinized as stand-alone values. The table below summarizes the individual findings for this FCA:

Facility (year built)	Cost/SF	Total SF	Replacement Value	Current	3-Year	5-Year	10-Year
Juniper Elementary School / Building 41-44	\$400	2,500	\$1,000,000	0.0%	4.7%	5.0%	17.1%
Juniper Elementary School / Building A	\$400	6,200	\$2,480,000	0.0%	0.0%	2.0%	8.0%
Juniper Elementary School / Building B	\$400	6,600	\$2,640,000	0.0%	1.7%	2.8%	9.3%
Juniper Elementary School / Building C	\$400	6,600	\$2,640,000	0.0%	0.0%	1.8%	6.7%
Juniper Elementary School / Building D	\$400	6,600	\$2,640,000	0.0%	0.0%	0.0%	4.2%
Juniper Elementary School / Building E	\$400	6,200	\$2,480,000	0.0%	0.0%	0.0%	4.6%
Juniper Elementary School / Building F	\$400	3,300	\$1,320,000	0.0%	0.0%	0.0%	5.9%
Juniper Elementary School / Building G	\$0	0	\$1	0.0%	0.0%	0.0%	0.0%
Juniper Elementary School / Portables	\$400	18,800	\$7,520,000	0.1%	0.1%	0.4%	5.2%

Immediate Needs

Facility/Bui	lding					Total Items		Total Cost
Juniper Eler	mentary School					1		\$7,600
Portables						1		\$4,900
Site						2		\$16,000
Total						4		\$28,500
Juniper Ele	mentary School							
ID O	Location.	Location Description	UF Code	Description		Condition	Plan Type	Cost
1313439	Juniper Elementary School	Throughout campus	P000X	Engineer, Civil	, Site/Storm Drainage, Evaluate/Report	NA	Performance/Integrity	\$7,600
Total (1 iter	ns)							\$7,600
Portables								
ID	Location	Location (Description	UF Code	Description	Condition	Plan Type	Cost
1312492	Juniper Elementary School / Portables	Main entra	nce ramps	C2011	Interior Stair/Ramp Rails, Wood, Repair	Poor	Performance/Integrity	\$4,900
Total (1 iter	ns)							\$4,900
Site								
ID	Location	Location Description	UF Code	Description		Condition	Plan Type	Cost
1312321	Juniper Elementary School / Site	Parking lot	G2022	Parking Lots, Asi	phall Pavement, Cut & Patch	Poor	Performance/Integrity	\$15,000
1314276	Juniper Elementary School / Site	Main entrance	Z105X	ADA, Miscellane	ous, Signage, Directional, Wall-Mounted, Install	NA	Accessibility	\$1,000
Total (2 iter	ms)							\$16,000

Key Findings



Secondary Transformer in Poor condition.

Dry, 30 kVA Site Site

Uniformat Code: D5012

Recommendation: Replace in 2020

Priority Score: 89.0

Plan Type:

Performance/Integrity

Cost Estimate: \$7,300

\$\$\$\$

The unit is rusty and not fully operational, replacement is recommended. - AssetCALC ID: 1312561



Secondary Transformer in Poor condition.

Dry, 30 kVA Site Site

Uniformat Code: D5012

Recommendation: Replace in 2020

Priority Score: 89.0

Plan Type:

Performance/Integrity

Cost Estimate: \$7,300

\$\$\$\$

The unit is rusty and not fully operational, replacement is recommended. - AssetCALC ID: 1312513



Parking Lots in Poor condition.

Asphalt Pavement Site Parking lot

Uniformat Code: G2022

Recommendation: Cut and Patch in 2019

Priority Score: 87.0


Plan Type:

Performance/Integrity

Cost Estimate: \$15,000

\$\$\$\$

Isolated areas of deteriorated asphalt, the repair is required. - AssetCALC ID: 1312321



Interior Stair/Ramp Rails in Poor condition.

Wood

Portables Main entrance ramps

Uniformat Code: C2011

Recommendation: Repair in 2019

Priority Score: 87.0

Plan Type:

Performance/Integrity

Cost Estimate: \$4,900

\$\$\$\$

The floor plywood is deteriorated, the repair is required. - AssetCALC ID: 1312492

Fire Alarm System in Poor condition.

Standard Addressable
Juniper Elementary School Throughout

Uniformat Code: D5037

Recommendation: Install in 2021

Priority Score: 87.0

Plan Type:

Performance/Integrity

Cost Estimate: \$240,300

\$\$\$\$

The system is reaching the end of its lifecycle and not fully operational, upgrading the fire alarm system is recommended. - AssetCALC ID: 1313424



Packaged Unit (RTU) in Poor condition.

3 Ton Building 41-44 Roof

Uniformat Code: D3052

Recommendation: Replace in 2020

Priority Score: **86.0**

Plan Type:

Performance/Integrity

Cost Estimate: \$8,200

\$\$\$\$

The unit is rusty and not fully operational, replacement is recommended. - AssetCALC ID: 1312382



Packaged Unit (RTU) in Poor condition.

20 Ton

Building B Ground level

Uniformat Code: D3052

Recommendation: Replace in 2020

Priority Score: 86.0

Plan Type:

Performance/Integrity

Cost Estimate: \$43,600

\$\$\$\$

The unit is rusty and not fully operational, replacement is recommended. - AssetCALC ID: 1312522



Packaged Unit (RTU) in Poor condition.

3 Ton

Building 41-44 Roof

Uniformat Code: D3052

Recommendation: Replace in 2020

Priority Score: 86.0

Plan Type:

Performance/Integrity

Cost Estimate: \$8,200

\$\$\$\$


The unit is rusty and not fully operational, replacement is recommended. - AssetCALC ID: 1312340

Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the "why" part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the "best" fit, typically the one with the greatest significance.

Plan Type Descriptions						
Safety	An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk.					
Performance/Integrity	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability.					
Accessibility	Does not meet ADA, UFAS, and/or other handicap accessibility requirements.					
Environmental	Improvements to air or water quality, including removal of hazardous materials from the building or site.					
Retrofit/Adaptation	 Components, systems, or spaces recommended for upgrades in in order to meet current standards, facility usage, or client/occupant needs. 					
Lifecycle/Renewal	Any component or system that is not currently deficient or problematic but for which future replacement or repair is anticipated and budgeted.					

Plan Type Distribution (by Cost)



2. Building 41-44





Building 41-44: Syst	tems Summary	
Address	1809 South Juniper Street, Escondido, California	
Constructed/Renovated	1959 / 2000	
Building Size	2,500 SF	
Number of Stories	One	
System	Description	Condition
Structure	Conventional wood-framed structure on concrete slabs	Good
Façade	Stucco with wood-framed windows	Fair
Roof	Primary: Flat construction with single-ply TPO/PVC membrane	Fair
Interiors	Walls: Painted gypsum board Floors: Carpet, VCT, sheet vinyl Ceilings: ACT	Fair
Elevators	None	
Plumbing	Copper supply, cast iron waste and vent Electric water heater Toilets and sinks in all restrooms	Fair
HVAC	Individual package units, only one new unit.	Poor
Fire Suppression	Hydrants, fire extinguishers	Fair
Electrical	Source and Distribution: Main panel with copper wiring fed from main switchboard Interior Lighting: T-8 Emergency: None	Fair
Fire Alarm	Smoke detectors, alarms	Fair
Equipment/Special	None	

Building 41-44: Systems Summary					
Accessibility	Presently it does not appear an accessibility study is needed for this property.				
Key Issues and Findings	Building lacks fire suppression, aged HVAC roof units				

See Appendix C for the Component Condition Table.

and the second second	Immediate	Short Term	Near Term	Med Term	Long Term	100
System		(3 yr)	(5 yr)	(10 yr)	(26 yr)	TOTAL
Facade	-	(e)	\$15,200	\$4,100	\$52,100	\$71,400
Roofing	le f	-		\$79,900	-	\$79,900
Interiors	8	\$21,100	\$10,200	-	\$66,100	\$97,400
Plumbing				\$5,400	\$21,400	\$26,800
HVAC		\$25,300		\$3,300	\$13,900	\$42,500
Electrical		\$2,400	-	\$600	- 3	\$3,000
Equipment/Special		F		\$21,100		\$21,100
TOTALS	-	\$48,800	\$25,400	\$114,400	\$153,500	\$342,100

3. Building A





Building A: Systems	Summary	
Address	1809 South Juniper Street, Escondido, California	
Constructed/Renovated	1959 / 2000	
Building Size	6,200 SF	
Number of Stories	One	
System	Description	Condition
Structure	Conventional wood-framed structure on concrete slabs	Good
Façade	Stucco with wood-framed windows	Fair
Roof	Primary: Gable construction with asphalt shingles	Fair
Interiors	Walls: Painted gypsum board and ceramic tiles Floors: Wood and ceramic tiles Ceilings: Painted gypsum board and ACT	Fair
Elevators	None	
Plumbing	Copper supply, cast iron waste and vent Gas-fired water heater Toilets and sinks in all restrooms	Fair
HVAC	Individual split systems Supplemental components: Ductless split system	Fair
Fire Suppression	Hydrants, fire extinguishers	Fair
Electrical	Source and Distribution: Main panel with copper wiring fed from main switchboard Interior Lighting: T-8 Emergency: none	Fair
Fire Alarm	Smoke detectors, alarms, strobes, pull stations	Fair


Building A: Systems Summary		
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression system	

See Appendix C for the Component Condition Table.

	Immediate	Short Term	Near Term	Med Term	Long Term	
System		(3 yr)	(5 yr)	(10 yr)	(20 yr)	TOTAL
Facade	11	-	\$32,300		\$67,600	\$99,900
Roofing		-	-	4	\$69,400	\$69,400
Interiors	(1)	16	\$15,200	\$32,700	\$120,600	\$168,500
Plumbing	1		-	\$7,000	\$9,700	\$16,700
HVAC	Ŧ		-	\$16,200	\$27,000	\$43,200
Electrical	9	\$47,700	**	\$7,500	\$4,200	\$59,400
Fire Alarm & Comm	-		-	\$20,700	-	\$20,700
Equipment/Special	1	~	\$1,900	\$14,900	\$2,500	\$19,400
TOTALS	3 11	\$47,700	\$49,400	\$99,000	\$301,000	\$497,200

4. Building B





Building B: Systems	Summary	
Address	1809 South Juniper Street, Escondido, California	
Constructed/Renovated	1959 / 2000	
Building Size	6,600 SF	
Number of Stories	One	
System	Description	Condition
Structure	Conventional wood-framed structure on concrete slabs	Good
Façade	Stucco with wood-framed windows	Fair
Roof	Primary: Gable construction with asphalt shingles	Fair
Interiors	Walls: Painted gypsum board and ceramic tiles Floors: VCT and ceramic tiles Ceilings: Painted gypsum board and ACT	Fair
Elevators	Wheelchair lift	Fair
Plumbing	Copper supply, cast iron waste and vent Gas-fired water heater Toilets and Sinks in all restrooms	Fair
HVAC	Individual package units	Fair
Fire Suppression	Hydrants, fire extinguishers	Fair
Electrical	Source and Distribution: Main panel with copper wiring fed from main switchboard Interior Lighting: T-8 Emergency: none	Fair
Fire Alarm	Smoke detectors, alarms, strobes, pull stations	Fair
Equipment/Special	Commercial kitchen equipment	Fair

Building B: Systems S	Summary
Accessibility	Presently it does not appear an accessibility study is needed for this property.
Key Issues and Findings	Building lacks fire suppression system

See Appendix C for the Component Condition Table.

	Immediate	Short Term	Near Term	Med Term	Long Term	
System		(3 yr)	(5 yr)	(10 yr)	(20 yr)	TOTAL
Facade	-		\$32,300	L	\$74,500	\$106,800
Roofing	-		1		\$79,900	\$79,900
Interiors			\$17,400	\$37,800	\$81,000	\$136,200
Elevators	-		*		\$29,500	\$29,500
Plumbing	-	9		\$9,100	\$22,300	\$31,400
HVAC		\$73,600		-	- 1	\$73,600
Electrical	~			~	\$4,200	\$4,200
Equipment/Special	_		\$17,700	\$72,200	\$25,000	5114,900
Site Development			1	\$13,900		\$13,900
TOTALS		\$73,600	\$67,400	\$133,000	\$316,400	\$590,400

5. Building C





Building C: Systems	Summary	
Address	1809 South Juniper Street, Escondido, California	
Constructed/Renovated	1959 / 2000	
Building Size	6,600 SF	
Number of Stories	One	
System	Description	Condition
Structure	Conventional wood-framed structure on concrete slabs	Good
Façade	Stucco with wood-framed windows	Fair
Roof	Primary: Gable construction with asphalt shingles	Fair
Interiors	Walls: Painted gypsum board and ceramic tiles Floors: Carpet and ceramic tiles Ceilings: Painted gypsum board and ACT	Fair
Elevators	None	
Plumbing	Copper supply, cast iron waste and vent Electric water heater Toilets, urinals and sinks in all restrooms	Fair
HVAC	Individual split systems	Excellent
Fire Suppression	Hydrants, fire extinguishers	Fair
Electrical	Source and Distribution: Main panel with copper wiring and switchboard with copper wiring Interior Lighting: T-8 Emergency: none	Fair
Fire Alarm	Smoke detectors, alarms, strobes, pull stations	Fair

Building C: Systems Summary		
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression system	

See Appendix C for the Component Condition Table.

	immediate	Short Term	Near Term	Med Term	Long Term	
System		(3 yr)	(5 yr)	(10 yr)	(20 yr)	TOTAL
Facade	-		\$32,300	-	\$74,300	\$106,500
Roofing	+		0.0	4	\$74,400	\$74,400
Interiors	-	-	574,200	\$5,000	\$169,500	\$248,700
Plumbing	-			\$13,400	\$29,900	\$43,300
HVAC	1	~			\$43,400	\$43,400
Electrical	-	\$47,700	8	\$9,800	\$11,100	\$68,500
TOTALS	-	\$47,700	\$106,500	528,200	\$402,600	\$584,800

6. Building D





Building D: Systems	Summary	
Address	1809 South Juniper Street, Escondido, California	
Constructed/Renovated	1959 / 2000	
Building Size	6,600 SF	
Number of Stories	One	
System	Description	Condition
Structure	Conventional wood-framed structure on concrete slabs	Good
Façade	Stucco with wood-framed windows	Fair
Roof	Primary: Gable construction with asphalt shingles	Fair
Interiors	Walls: Painted gypsum board Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	Copper supply, cast iron waste and vent No hot water Sinks in classrooms	Fair
HVAC	Individual split systems	Excellent
Fire Suppression	Hydrants, fire extinguishers	Fair
Electrical	Source and Distribution: Main panel with copper wiring fed from main switchboard Interior Lighting: T-8 Emergency: none	Fair
Fire Alarm	Smoke detectors, alarms, strobes, pull stations	Fair
Equipment/Special	None	

Building D: Systems S	Summary
Accessibility	Presently it does not appear an accessibility study is needed for this property.
Key Issues and Findings	Building lacks fire suppression system

See Appendix C for the Component Condition Table.

	Immediate	Short Term	Near Term	Med Term	Long Term	
System		(3 yr)	(5 yr)	(10 yr)	(20 yr)	TOTAL
Facade		-	\$32,300	-	\$85,300	\$117,600
Roofing			3	-	\$74,400	574,400
Interiors		- 0	\$68,300	ŧ	\$132,100	\$200,400
Plumbing	-		-		\$11,900	\$11,900
HVAC	-				\$52,500	\$52,500
Electrical				\$5,400		\$5,400
Equipment/Special				\$26,400		\$26,400
TOTALS	41	19	\$100,600	\$31,800	\$356,200	\$488,600

7. Building E





Building E: Systems	Summary	
Address	1809 South Juniper Street, Escondido, California	
Constructed/Renovated	1959 / 2000	
Building Size	6,200 SF	
Number of Stories	One	
System	Description	Condition
Structure	Conventional wood-framed structure on concrete slabs	Good
Façade	Stucco with wood-framed windows	Fair
Roof	Primary: Gable construction with asphalt shingles	Fair
Interiors	Walls: Painted gypsum board and ceramic tiles Floors: Carpet and ceramic tiles Ceilings: Painted gypsum board and ACT	Fair
Elevators	None	
Plumbing	Copper supply, cast iron waste and vent No hot water Toilets, urinals and sinks in all restrooms	Fair
HVAC	Individual split systems and one package unit	Good
Fire Suppression	Hydrants, fire extinguishers	Fair
Electrical	Source and Distribution: Fed from main panel and switchboard with copper wiring Interior Lighting: T-8 Emergency: none	Fair
Fire Alarm	Smoke detectors, alarms, strobes, pull stations	Fair
Equipment/Special	None	

Building E: Systems	Summary
Accessibility	Presently it does not appear an accessibility study is needed for this property.
Key Issues and Findings	Building lacks fire suppression system

See Appendix C for the Component Condition Table.

	Immediate	Short Term	Near Term	Med Term	Long Term	
System		(3 yr)	(5 yr)	(10 yr)	(20 yr)	TOTAL
Facade	+	+	\$36,000		\$80,500	\$116,500
Roofing	£	- 6		12	\$68,000	\$68,000
Interiors			\$72,200	\$7,500	\$166,800	\$246,500
Plumbing			-		\$35,600	\$35,600
HVAC	=			1	\$65,400	\$65,400
Electrical		-		\$1,200	-	\$1,200
Equipment/Special				\$31,700		\$31,700
TOTALS	40		\$108,200	\$40,400	\$416,300	\$564,900

8. Building F





Building F: Systems	Summary	
Address	1809 South Juniper Street, Escondido, California	
Constructed/Renovated	1959 / 2000	
Building Size	3,300 SF	
Number of Stories	One	
System	Description	Condition
Structure	Conventional wood-framed structure on concrete slabs	Good
Façade	Stucco with wood-framed windows	Fair
Roof	Primary: Gable construction with asphalt shingles	Fair
Interiors	Walls: Painted gypsum board and ceramic tile Floors: Carpet, VCT, ceramic tile Ceilings: Painted gypsum board and ACT	Fair
Elevators	None	
Plumbing	Copper supply, cast iron waste and vent No hot water Toilets and sinks in all restrooms	Fair
HVAC	Individual split systems	Excellent
Fire Suppression	Hydrants, fire extinguishers	Fair
Electrical	Source and Distribution: Fed from main panel and switchboard with copper wiring Interior Lighting: T-8 Emergency: none	Fair
Fire Alarm	Smoke detectors, alarms, strobes, pull stations	Fair
Equipment/Special	None	

Building F: Systems Summary		
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression system	

See Appendix C for the Component Condition Table.

System	Immediate	Shart Term	Near Term	Med Term (10 yr)	Long Term (20 yr)	TOTAL
System		(3 yr)	(5 yr)	(10.31)	(20 yi)	TOTAL
Facade	-		\$24,700	-	\$51,600	\$76,200
Roofing	2	1	- a	i	\$44,500	\$44,500
Interiors			\$42,600	\$1,900	\$92,400	\$137,000
Plumbing				\$5,000	\$12,100	\$17,000
HVAC		1			\$23,400	\$23,400
Electrical	-	-	3	\$600	\$11,700	\$12,300
Equipment/Special	-			\$9,700	-	\$9,700
TOTALS	×		\$67,300	\$17,200	\$235,700	\$320,100

9. Building G





Building G: Systems	Summary Summary	
Address	1809 South Juniper Street, Escondido, California	
Constructed/Renovated	1959 / 2000	
Building Size	3,300 SF	
Number of Stories	One	
System	Description	Condition
Structure	Conventional wood-framed structure on concrete slabs	Good
Façade	Stucco with wood-framed windows	Fair
Roof	Primary: Gable construction with asphalt shingles	Fair
Interiors	Walls: Painted gypsum board Floors: carpet Ceilings: Painted gypsum board	Fair
Elevators	None	
Plumbing	Copper supply, cast iron waste and vent No hot water Sinks in classrooms	Fair
HVAC	Individual split systems	Excellent
Fire Suppression	None	
Electrical	Source and Distribution: Fed from adjacent building with copper wiring Interior Lighting: T-8 Emergency: none	Fair
Fire Alarm	Smoke detectors, alarms, strobes, pull stations	Fair
Equipment/Special	None	

Building G: Systems Summary		
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression system	

See Appendix C for the Component Condition Table.

System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
		19.311		(neyi)	70.00	
Facade			\$17,100		\$53,200	\$70,300
Roofing	1=1		1.5	-	\$46,200	\$46,200
Interiors		9	- 1	\$39,100	\$69,400	\$108,500
Plumbing			-		\$6,300	\$6,300
HVAC	-				\$25,700	\$25,700
Electrical				\$1,200	\$10,700	\$12,000
Equipment/Special	-	1		\$14,100		\$14,100
TOTALS		*	\$17,100	\$54,400	\$211,500	\$283,100

10. Portables





Portables : Systems	Summary	
Address	1809 South Juniper Street, Escondido, California	
Constructed/Renovated	2000	
Building Size	18,800 SF	
Number of Stories	One	
System	Description	Condition
Structure	Conventional wood-framed structure with raised floor	Good
Façade	Wood siding with aluminum-framed windows	Fair
Roof	Primary: Flat construction with metal finish and modified bituminous finish	Fair
Interiors	Walls: Fabric and ceramic tile Floors: Carpet, VCT, sheet vinyl, and ceramic tile Ceilings: ACT	Fair
Elevators	None	
Plumbing	Copper supply, cast iron waste and vent No hot water Toilets, urinals and sinks in all restrooms	Good
HVAC	Heat pump units	Fair
Fire Suppression	Hydrants, fire extinguishers	Fair
Electrical	Source and Distribution: Fed from main panels and switchboard with copper wiring Interior Lighting: T-8 Emergency: none	Fair
Fire Alarm	Smoke detectors, alarms, strobes, pull stations	Fair
Equipment/Special	None	

Portables : Systems Summary					
Accessibility	Accessibility Presently it does not appear an accessibility study is needed for this property.				
Key Issues and Findings	Buildings lack fire suppression systems, deteriorated portable ramp entrance.				

See Appendix C for the Component Condition Table.

	Immediate	Short Term	Near Term	Med Term	Long Term	
System		(3 yr)	(5 yr)	(10 yr)	(20 yr)	TOTAL
Structure	-	10	\$1,100	net .	\$1,400	\$2,500
Facade	= =		\$87,300	\$5,200	\$178,800	\$271,300
Roofing		1		\$13,200		\$13,200
Interiors	54,900	4	\$170,700	580,300	\$355,800	5611,700
Plumbing		1		\$10,200	\$12,000	\$22,300
HVAC		\$26,200		\$120,900		\$147,200
Electrical	-		1		\$1,100	\$1,100
TOTALS	\$4,900	\$26,200	\$259,100	\$229,800	\$549,100	\$1,069,300

11. Site Summary





Site Information		
Lot Size	10.38 acres (estimated)	
Parking Spaces	82 total spaces all in open lots; four of which are accessible	
System	Description	Condition
Pavement/Flatwork	Asphalt lots with areas of concrete and concrete sidewalks, curbs and ramps	Fair
Site Development	Property entrance signage, wrought iron fencing Playgrounds and sports courts with bleachers, fencing	Fair
Landscaping and Topography	Moderate landscaping features Irrigation present Retaining wall adjacent to lunch shelter Low to moderate site slopes throughout	Fair
Utilities	Municipal water and sewer Local utility-provided electric	Fair
Site Lighting	Pole-mounted: none Building-mounted: LED, and metal halide	Fair
Ancillary Structures	None	<u> </u>
Accessibility	Presently it does not appear an accessibility study is needed for the exterior site are C.	eas. See Appendix
Key Issues and Findings	Isolated areas of alligator parking lot cracking, significant sidewalk trip hazards due aged electrical infrastructure.	to uneven surface,

See Appendix C for the Component Condition Table.

System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Roofing	=	8	8	- 1	\$73,800	\$73,800
Plumbing	-	-	\$4,600	-	\$42,500	\$47,000
Fire Suppression	-	100		91	\$28,000	\$28,000
Electrical		\$15,100	i.	-	\$10,400	\$25,500
Site Development		\$18,200	4	\$185,600	\$287,200	\$491,000
Landscaping	-			- 9	3860,200	\$869,200
Pavement	\$15,000	\$37,200		\$322,100	\$91,600	\$466,100
Accessibility	\$1,000	-		- 2		\$1,000
TOTALS	\$16,000	\$70,500	\$4,600	\$508,200	\$1,403,600	\$2,002,900

12. ADA Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) applies to State and local government entities. Title II Subtitle A protects qualified individuals with disabilities from discrimination on the basis of disability in services, programs, and activities provided by state and local government entities. Title II extends the prohibition on discrimination established by section 504 of the Rehabilitation Act of 1973, as amended, 29 U.S.C. 794, to all activities of state and local governments, regardless of Federal financial assistance. All state and local government facilities must be maintained and operated in compliance with the Americans with Disabilities Act Accessibility Guidelines (ADAAG). In addition, in the state of California, compliance with the California Building Code (CBC) Chapter 11 Accessibility to Public Buildings, Public Accommodations, Commercial Buildings, and Publicly Funded Housing is required.

During the FCA, a limited visual observation for accessibility compliance was conducted. The scope of the visual observation was limited to those areas set forth in EMG's Abbreviated ADA Checklist, provided in Appendix D of this report. It is understood by the Client that the limited observations described herein does not comprise a full Accessibility Compliance Survey, and that such a survey is beyond the scope of EMG's undertaking for this report. The Abbreviated ADA Checklist targets key areas for compliance with 2010 ADA Standards for Accessible Design and does not include California Building Code accessibility requirements. A full Accessibility Compliance Survey conducted by EMG would include both ADA and State of California accessibility requirements. For the FCA, only a representative sample of areas was observed and, other than those shown on the Abbreviated ADA Checklist, actual measurements were not taken to verify compliance.

The facility generally appears to be accessible as stated within the defined priorities of Title II of the Americans with Disabilities Act.

Parking

Signage directing to accessible parking or accessible building entrances to the facility are not provided.

A full Accessibility Compliance Survey may reveal additional aspects of the property that are not in compliance.

Corrections of these conditions should be addressed from a liability standpoint but are not necessarily code violations. The Americans with Disabilities Act Accessibility Guidelines concern civil rights issues as they pertain to the disabled and are not a construction code, although many local jurisdictions have adopted the Guidelines as such. The cost to address the achievable item noted above is included in the Immediate Repairs Report.

Photos of the issues encountered are included in the photolog.

13. Purpose and Scope

Purpose

EMG was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

Condition Ratings	
Excellent	New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Good	Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Fair	Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.
Poor	Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life.
Failed	Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.
Not Applicable	Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.

Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans
 with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for
 further review.

- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding
 of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior
 common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.

14. Opinions of Probable Costs

Cost estimates are attached throughout this report, with the Replacement Reserves in the appendix.

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means, CBRE Whitestone,* and *Marshall & Swift,* EMG's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, EMG opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its effective age, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of EMG's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

Definitions

Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with *Safety* or *Performance/Integrity* Plan Types, are considered Immediate Needs.

Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, EMG's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

EMG's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system's or component's respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.

Exceedingly Aged

A fairly common scenario encountered during the assessment process, and a frequent source of debate, occurs when classifying and describing "very old" systems or components that are still functioning adequately and do not appear nor were reported to be in any way deficient. To help provide some additional intelligence on these items, such components will be tagged in the database as Exceedingly Aged. This designation will be reserved for mechanical or electrical systems or components that have aged well beyond their industry standard lifecycles, typically at least 15 years beyond and/or twice their Estimated Useful Life (EUL). In tandem with this designation, these items will be assigned a Remaining Useful Life (RUL) not less than two years but not greater than 1/3 of their standard EUL. As such the recommended replacement time for these components will reside outside the typical Short Term window but will not be pushed 'irresponsibly' (too far) into the future.

15. Certification

DLR Group (the Client) retained EMG to perform this Facility Condition Assessment in connection with its Facility Master Planning effort for the Escondido Union School District at Juniper Elementary School, 1809 South Juniper Street, Escondido, California 92025, the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared on behalf of and exclusively for the use of the Client for the purpose stated within the *Purpose and Scope* section of this report. The report, or any excerpt thereof, shall not be used by any party other than the Client or for any other purpose than that specifically stated in our agreement or within the *Purpose and Scope* section of this report without the express written consent of EMG.

Any reuse or distribution of this report without such consent shall be at the Client and the recipient's sole risk, without liability to EMG.

Prepared by: Nezar M. Tibi,

Project Manager

Reviewed by:

Alex Israel,

Technical Report Reviewer for

Mark Surdam Program Manager

msurdam@emgcorp.com

800.733.0660 x6251

16. Appendices

Appendix A: Photographic Record

Appendix B: Site Plans

Appendix C: Component Condition Table


Appendix D: ADA Checklist

Appendix E: Pre-Survey Questionnaire


Appendix F: Replacement Reserves

Appendix G: Equipment Inventory List

Appendix A: Photographic Record









#8 BUILDING G



#9 PORTABLES



NEW RESTROOMS

#10



#11 PARKING LOT ENTRANCE



#12 PARKING LOTS



#13 PARKING LOTS



#14 PARKING LOTS



#15 EXTERIOR RAMP



#16 FENCES AND GATES



#17 PEDESTRIAN PAVEMENT



#18 PLAY STRUCTURE



#19 PLAYGROUND



#20 LUNCH SHELTER



#21 ROOF



#22 ROOF



#23 BUILDING 41-44 ROOF



#24 PORTABLE ROOFS







#26 EXTERIOR WINDOWS



#27 PORTABLE WINDOW



#28 INTERIOR DOOR



#29 PACKAGE UNIT



#30 PACKAGE UNIT



#31 NEW SPLIT SYSTEM CONDENSING UNIT



#32 GROUND LEVEL PACKAGE UNIT



#33 EXHAUST FAN



ABOVE CEILING AIR HANDLER

#34



#35 AIR HANDLER



#36 HEAT PUMPS



#37 WATER HEATER



#38 WATER HEATER



#39 SWITCHBOARD



RUSTY TRANSFORMER

#40



#41 DISTRIBUTION PANEL




#42 WHEELCHAIR LIFT



#43 FRONT OFFICE




#44 OFFICE



#45 LOUNGE



#46 LIBRARY



#47 MPR



#48 CLASSROOM



#49 CLASSROOM



#50 CLASSROOM



#51 CLASSROOM



#52 KITCHEN



#53 KITCHEN



#54 KITCHEN SINK



#55 TOILET PARTITIONS



#56 RESTROOM



#57 RESTROOM



#58 RESTROOM




#59 EXTERIOR DRINKING FOUNTAIN



#60 SERVICE SINK

Appendix B: Site Plans

Site Plan



SOURCE:

Client



Aerial Site Plan



SOURCE:

Google Maps: Imagery ©2018 Google, Map data ©2019 Google



ON-SITE DATE:

June 27, 2019

Appendix C:
Component Condition Table

Component Condition Report

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building exterior	Fair	Exterior Stair/Ramp Rails, Metal, Refinish	560 LF	5	1312510
B1015	Throughout the site	Fair	Exterior Stair/Ramp Rails, Metal, Refinish	280 LF	6	1312466
Facade						
B2011	Building Exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	6,500 SF	5	1312285
B2011	Building Exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	4,500 SF	5	1312455
B2011	Building exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	8,500 SF	5	1312520
B2011	Building Exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	8,500 SF	5	1312385
B2011	Building Exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	23,000 SF	5	1312282
B2011	Building Exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	9,500 SF	5	1312529
B2011	Building Exterior- new restroom	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,300 SF	7	1312329
B2011	Building Exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	8,500 SF	5	1312533
B2011	Building exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	4,000 SF	5	1312465
B2011	Building Exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	8,500 SF	5	1312527
B2021	Building Exterior	Fair	Window, Aluminum Double-Glazed 24 SF, 1-2 Stories	38	11	1312309
B2021	Building exterior	Fair	Window, Wood 24 SF, 1-2 Stories	16	14	1312416
B2021	Building Exterior	Fair	Window, Wood 12 SF, 1-2 Stories	16	14	1312374
B2021	Building Exterior	Fair	Window, Wood 12 SF, 1-2 Stories	8	14	1312287
B2021	Building Exterior	Fair	Window, Wood 24 SF, 1-2 Stories	12	14	1312511
B2021	Building Exterior	Fair	Window, Wood 12 SF, 1-2 Stories	14	14	1312512
B2021	Building Exterior	Fair	Window, Wood 12 SF, 1-2 Stories	12	14	1312488
B2021	Building Exterior	Fair	Window, Wood 24 SF, 1-2 Stories	18	14	1312469
B2021	Building Exterior	Fair	Window, Wood 12 SF, 1-2 Stories	15	14	1312323
B2032	Building Exterior	Fair	Exterior Door, Wood Solid-Core	7	13	1312271
B2032	Building Exterior	Fair	Exterior Door, Wood Solid-Core	12	11	1312485
B2032	Building Exterior	Fair	Exterior Door, Steel	10	18	1312504
B2032	Building Exterior	Fair	Exterior Door, Wood Solid-Core	6	11	1312353
B2032	Building Exterior	Fair	Exterior Door, Steel	22	21	1312497
B2032	Building Exterior	Fair	Exterior Door, Wood Solid-Core	8	11	1312389
B2032	Building Exterior	Fair	Exterior Door, Wood Solid-Core	6	12	1312505
B2032	Building exterior	Fair	Exterior Door, Wood Solid-Core	4	10	1312320
B2032	New restrooms	Good	Exterior Door, Steel	4	38	1312556
B2032	Building Exterior	Fair	Exterior Door, Wood Solid-Core	10	12	1312414
Roofing						
B3011	Roof	Fair	Roof, Asphalt Shingle 30-Year	7,950 SF	12	1312401
B3011	Roof	Fair	Roof, Single-Ply TPO/PVC Membrane	3,400 SF	8	1312270
B3011	Walkway area roof	Fair	Roof, Asphalt Shingle 30-Year	2,200 SF	14	1312573
B3011	Roof	Fair	Roof, Asphalt Shingle 30-Year	7,650 SF	14	1312311
B3011	Roof	Fair	Roof, Asphalt Shingle 30-Year	8,300 SF	16	1312302
B3011	Roof	Fair	Roof, Asphalt Shingle 30-Year	8,200 SF	14	1312548

Component C	Condition Report			שויפווע יי ורשו ע	นเจดเมอดแดเ	11 1. (11 18 08 08 8
UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
B3011	Lunch shelter	Fair	Roof, Metal	2,100 SF	20	1312408
B3011	Roof	Fair	Roof, Metal	24,000 SF	21	1312435
B3011	Roof	Fair	Roof, Asphalt Shingle 30-Year	4,800 SF	16	1312275
B3011	Roof	Fair	Roof, Asphalt Shingle 30-Year	4,900 SF	14	1312360
B3011	Roof- restroom	Fair	Roof, Modified Bituminous	900 SF	10	1312506
B3011	Roof	Fair	Roof, Asphalt Shingle 30-Year	8,200 SF	14	1312474
Interiors						
C1021	Throughout	Fair	Interior Door, Wood Solid-Core	8	18	1312387
C1021	Throughout	Fair	Interior Door, Wood Solid-Core	6	18	1312341
C1021	Building interior	Fair	Interior Door, Wood Solid-Core	3	18	1312409
C1021	Building interior	Fair	Interior Door, Wood Solid-Core	8	18	1312496
C1021	Building interior	Fair	Interior Door, Wood Solid-Core	6	18	1312452
C1021	Building interior	Fair	Interior Door, Wood Solid-Core	6	18	1312419
C1021	Building interior-45	Fair	Interior Door, Wood Solid-Core	6	21	1312410
C1021	Building interior	Fair	Interior Door, Wood Solid-Core	8	18	1312463
C1023	Throughout	Fair	Door Hardware System, School (per Door)	140	15	1313423
C1031	Common area restrooms	Fair	Toilet Partitions, Metal	6	10	1312567
C1031	Common area restrooms	Fair	Toilet Partitions, Metal	2	10	1312319
C1031	Common area restrooms	Fair	Toilet Partitions, Metal	4	10	1312475
C1031	Common area restrooms	Fair	Toilet Partitions, Metal	10	10	1312388
C2011	Main entrance ramps	Poor	Interior Stair/Ramp Rails, Wood, Repair	300 LF	0	1312492
C3012	Common area restrooms	Fair	Interior Wall Finish, Ceramic Tile	550 SF	18	1312303
C3012	Throughout	Fair	Interior Wall Finish, any surface, Prep & Paint	6,500 SF	5	1312376
C3012	Throughout	Fair	Interior Wall Finish, any surface, Prep & Paint	8,500 SF	5	1312404
C3012	Common area restrooms	Fair	Interior Wall Finish, Ceramic Tile	550 SF	18	1312489
C3012	Throughout	Fair	Interior Wall Finish, any surface, Prep & Paint	4,000 SF	5	1312357
C3012	Restroom	Fair	Interior Wall Finish, Ceramic Tile	220 SF	18	1312481
C3012	Throughout	Fair	Interior Wall Finish, any surface, Prep & Paint	8,500 SF	5	1312393
C3012	Throughout	Fair	Interior Wall Finish, any surface, Prep & Paint	4,500 SF	6	1312391
C3012	Throughout	Fair	Interior Wall Finish, any surface, Prep & Paint	8,500 SF	5	1312317
C3012	Portables	Fair	Interior Wall Finish, Fabric	22,000 SF	8	1312517
C3012	Common area restrooms	Fair	Interior Wall Finish, Ceramic Tile	500 SF	18	1312396
C3012	Restroom	Fair	Interior Wall Finish, Ceramic Tile	320 SF	18	1312413
C3012	Throughout	Fair	Interior Wall Finish, any surface, Prep & Paint	9,500 SF	5	1312501
		Fair		460 SF	18	
C3012	Common area restrooms		Interior Wall Finish, Ceramic Tile			1312544
C3012	Throughout	Fair	Interior Wall Finish, any surface, Prep & Paint	7,500 SF	5	1312386
C3024	Restroom	Fair	Interior Floor Finish, Ceramic Tile	160 SF	18	1312446
C3024	Throughout	Fair	Interior Floor Finish, Vinyl Tile (VCT)	5,800 SF	6	1312327
C3024	Throughout	Fair	Interior Floor Finish, Vinyl Tile (VCT)	760 SF	8	1312462
C3024	Throughout	Fair	Interior Floor Finish, Linoleum	600 SF	8	1312541
C3024	Common area restrooms	Fair	Interior Floor Finish, Ceramic Tile	350 SF	18	1312545

Component C	Condition Report					
UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
C3024	Restroom	Fair	Interior Floor Finish, Vinyl Sheeting	120 SF	5	1312442
C3024	Common area restrooms	Fair	Interior Floor Finish, Ceramic Tile	300 SF	18	1312362
C3024	Common area restrooms	Fair	Interior Floor Finish, Ceramic Tile	360 SF	18	1312400
C3024	Common area restrooms	Fair	Interior Floor Finish, Ceramic Tile	360 SF	18	1312350
C3024	Restroom	Fair	Interior Floor Finish, Ceramic Tile	220 SF	18	1312572
C3024	Restroom-46	Fair	Interior Floor Finish, Vinyl Sheeting	180 SF	8	1312284
C3024	Throughout	Fair	Interior Floor Finish, Vinyl Tile (VCT)	240 SF	5	1312312
C3024	Throughout	Fair	Interior Floor Finish, Vinyl Tile (VCT)	280 SF	8	1312286
C3025	Throughout	Fair	Interior Floor Finish, Carpet Commercial Standard	5,500 SF	5	1312420
C3025	Throughout	Fair	Interior Floor Finish, Carpet Commercial Standard	3,100 SF	5	1312306
C3025	Throughout	Poor	Interior Floor Finish, Carpet Commercial Standard	2,500 SF	1	1312343
C3025	Throughout	Fair	Interior Floor Finish, Carpet Commercial Standard	2,800 SF	6	1312335
C3025	Throughout	Fair	Interior Floor Finish, Carpet Commercial Standard	5,500 SF	5	1312398
C3025	Throughout	Fair	Interior Floor Finish, Carpet Commercial Standard	18,000 SF	5	1312381
C3025	Throughout	Fair	Interior Floor Finish, Carpet Commercial Standard	6,000 SF	5	1312502
C3025	Throughout	Fair	Interior Floor Finish, Carpet Commercial Standard	3,100 SF	6	1312363
C3031	Throughout	Fair	Interior Ceiling Finish, any flat surface, Prep & Paint	400 SF	5	1312430
C3031	Restroom	Fair	Interior Ceiling Finish, any flat surface, Prep & Paint	340 SF	5	1312439
C3031	Throughout	Fair	Interior Ceiling Finish, any flat surface, Prep & Paint	500 SF	5	1312537
C3031	Common area restrooms	Fair	Interior Ceiling Finish, any flat surface, Prep & Paint	460 SF	5	1312552
C3031	Throughout	Fair	Interior Ceiling Finish, any flat surface, Prep & Paint	800 SF	5	1312532
C3032	Throughout	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	5,800 SF	12	1312361
C3032	Throughout	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	5,800 SF	13	1312290
C3032	Throughout	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	18,000 SF	13	1312351
C3032	Throughout	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	5,800 SF	12	1312531
C3032	Throughout	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	5,800 SF	13	1312337
C3032	Throughout	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	2,500 SF	11	1312543
C3032	Throughout	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	4,500 SF	12	1312523
C3032	Throughout	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	3,100 SF	12	1312445
C3032	Throughout	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	2,800 SF	12	1312422
Elevators						
D1013	Stage	Fair	Wheelchair Lift, 5' Rise, Renovate	1	13	1312339
Plumbing						
D2011	Restroom	Fair	Toilet, Tankless (Water Closet)	4	14	1312356
D2011	New restroom	Good	Toilet, Tankless (Water Closet)	14	27	1312515
D2011	Common area restrooms	Fair	Toilet, Tankless (Water Closet)	3	15	1312324
D2011	Restroom-46	Fair	Toilet, Tankless (Water Closet)	2	16	1312349
D2011	Restroom	Fair	Toilet, Tankless (Water Closet)	6	14	1312371
D2011	Restroom	Fair	Toilet, Tankless (Water Closet)	4	14	1312415
D2011	Common area restrooms	Fair	Toilet, Tankless (Water Closet)	6	14	1312359
D2011	Restroom	Fair	Toilet, Tankless (Water Closet)	3	16	1312503

Component C	Condition Report				ON SERVICE STATES	M PUMPOSES
UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D2012	Common area restrooms	Fair	Urinal, Standard	2	14	1312305
D2012	Common area restrooms	Fair	Urinal, Standard	3	18	1312479
D2012	Common area restrooms	Fair	Urinal, Standard	2	14	1312507
D2014	Common area restrooms	Fair	Sink/Lavatory, Wall-Hung, Vitreous China	2	14	1312273
D2014	Kitchen	Fair	Commercial Kitchen Sink, Stainless Steel, 1-Bowl	1	16	1312407
D2014	Throughout	Fair	Sink/Lavatory, Vanity Top, Stainless Steel	3	10	1312326
D2014	Throughout	Fair	Sink/Lavatory, Vanity Top, Stainless Steel	4	14	1312291
D2014	Custodian closet	Fair	Service Sink, Wall-Hung	1	15	1312554
D2014	New restrooms	Good	Sink/Lavatory, Wall-Hung, Vitreous China	11	27	1312429
D2014	Kitchen	Fair	Commercial Kitchen Sink, Stainless Steel, 3-Bowl	1	16	1312277
D2014	Janitor room	Fair	Service Sink, Wall-Hung	2	10	1312486
D2014	Throughout	Fair	Sink/Lavatory, Vanity Top, Stainless Steel	3	14	1312480
D2014	Common area restrooms	Fair	Sink/Lavatory, Wall-Hung, Vitreous China	6	14	1312491
D2014	Restroom	Fair	Sink/Lavatory, Wall-Hung, Vitreous China	3	14	1312468
D2014	Restroom-46	Fair	Sink/Lavatory, Wall-Hung, Vitreous China	1	16	1312460
D2014	Building interior	Fair	Sink/Lavatory, Vanity Top, Stainless Steel	4	14	1312412
D2014	Custodian closet	Fair	Service Sink, Wall-Hung	1	13	1312553
D2014	Throughout	Fair	Sink/Lavatory, Vanity Top, Solid Surface or Vitreous China	5	6	1312436
D2014	Throughout	Fair	Sink/Lavatory, Vanity Top, Stainless Steel	6	14	1312418
D2014	Common area restrooms	Fair	Sink/Lavatory, Wall-Hung, Vitreous China	6	14	1312283
D2014	Throughout	Fair	Sink/Lavatory, Vanity Top, Stainless Steel	3	16	1312380
D2014	Restroom	Fair	Sink/Lavatory, Wall-Hung, Vitreous China	2	14	1312535
D2018	Building exterior	Fair	Drinking Fountain, Outside/Site Style	1	8	1312550
D2018	Building exterior	Fair	Drinking Fountain, Outside/Site Style	1	8	1312383
D2018	Site- adjacent to portable	Fair	Drinking Fountain, Outside/Site Style	1	5	1312471
D2018	Building exterior	Fair	Drinking Fountain, Outside/Site Style	2	9	1312293
D2018	Building exterior	Fair	Drinking Fountain, Outside/Site Style	1	8	1312268
D2018	Building exterior	Fair	Drinking Fountain, Outside/Site Style	1	6	1312301
D2021	Site	Fair	Backflow Preventer, Domestic, 3"	1	16	1312428
D2021	Site	Fair	Backflow Preventer, Domestic, 3"	1	16	1312569
D2021	Site	Fair	Backflow Preventer, Domestic, 3"	1	14	1312443
D2021	Site	Fair	Backflow Preventer, Domestic, 3"	1	14	1312299
D2023	Janitor room	Good	Water Heater, Gas, Residential, 75 GAL	1	11	1312534
D2023	Custodian room	Fair	Water Heater, Gas, Residential, 50 GAL	1	7	1312310
D2023	Janitor room	Fair	Water Heater, Electric, Residential, 30 GAL	1	8	1312348
D2023	Site	Excellent	Domestic Circulation/Booster Pump, 5 HP	1	25	1312564
D2023	Custodian closet	Fair	Water Heater, Electric, Residential, 15 GAL	1	7	1312441
D2029	Throughout	Fair	Plumbing System, Supply & Sanitary, Low Density (excl fixtures)	55,066 SF	18	1313427
D2042	Throughout	Poor	Roof Drain, 2"	90	2	1313441
Fire Suppressi	on					
D4011	Site	Fair	Backflow Preventer, Fire Suppression, 10"	1	12	1312549

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
HVAC						
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	15	1312570
D3032	Building E	Excellent	Condensing Unit/Heat Pump, Split System, 3.5 Ton	1	14	1312546
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	14	1312390
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 5 Ton	1	14	1312296
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	14	1312514
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	15	1312433
D3032	Roof	Fair	Condensing Unit/Heat Pump, Split System, 3 Ton	1	11	1312453
D3032	Roof	Good	Condensing Unit/Heat Pump, Split System, 4 Ton	1	12	1312280
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	15	1312482
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	14	1312354
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 5 Ton	1	14	1312288
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	14	1312272
D3032	Roof	Fair	Condensing Unit/Heat Pump, Split System, 5 Ton	1	7	1312403
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	14	1312461
D3032	Roof	Good	Condensing Unit/Heat Pump, Split System, 3 Ton	1	11	1312322
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	14	1312519
D3032	Roof	Fair	Ductless Split System, Single Zone, 2 Ton	1	8	1312384
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	14	1312342
D3032	Roof	Good	Condensing Unit/Heat Pump, Split System, 4 Ton	1	12	1312373
D3032	Roof	Excellent	Condensing Unit/Heat Pump4 Ton, Split System, 4 Ton	1	15	1312394
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	15	1312484
D3032	Roof	Good	Condensing Unit/Heat Pump, Split System, 3.5 Ton	1	11	1312490
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	15	1312372
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 4 Ton	1	14	1312379
D3032	Roof	Excellent	Condensing Unit/Heat Pump, Split System, 3 Ton	1	15	1312294
D3041	Attic	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312344
D3041	Attic	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312571
D3041	Above ceiling	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312558
D3041	Attic	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312440
D3041	Above ceiling	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312483
D3041	Attic	Good	Air Handler (AHU), Interior, 1,600 CFM	1	22	1312297
D3041	Attic	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312289
D3041	Attic	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312500
D3041	Attic	Fair	Air Handler (AHU), Interior, 400 CFM	1	20	1312365
D3041	Utility closet	Excellent	Air Handler (AHU), Interior, 2,000 CFM	1	24	1312530
D3041	Attic	Good	Air Handler (AHU), Interior, 1,200 CFM	1	22	1312417
D3041	Attic	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312494
D3041	Attic	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312336
D3041	Attic	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312369
D3041	Attic	Excellent	Air Handler (AHU), Interior, 400 CFM	1	25	1312316

omponom o	ondition Report					n Purpose
F Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
03041	Attic	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312364
03041	Utility closet	Excellent	Air Handler (AHU), Interior, 2,000 CFM	1	24	1312432
03041	Attic	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312498
D3041	Above ceiling	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312528
D3041	Attic	Excellent	Air Handler (AHU), Interior, 1,600 CFM	1	25	1312358
03041	Attic	Good	Air Handler (AHU), Interior, 1,000 CFM	1	22	1312516
03041	Attic	Good	Air Handler (AHU), Interior, 1,600 CFM	1	22	1312487
03041	Attic	Fair	Air Handler (AHU), Interior, 400 CFM	1	20	1324927
03042	Roof	Fair	Exhaust Fan, Roof or Wall Mounted, 50 to 500 CFM	1	8	1312278
03042	Roof	Fair	Exhaust Fan, Roof or Wall Mounted, 50 to 500 CFM	1	8	1312347
03052	Rear of building-46	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	3	1312397
03052	Rear of building-25	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312292
03052	Rear of building-23	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312425
D3052	Roof	Fair	Packaged Unit (RTU), 7.5 Ton	1	3	1312325
03052	Rear of building-07	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	3	1312508
03052	Rear of building-36	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312330
3052	Roof	Excellent	Packaged Unit (RTU), 7.5 Ton	1	19	1312521
3052	Roof	Good	Packaged Unit (RTU), 3 Ton	1	18	1312370
3052	Rear of building-33	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312355
3052	Rear of building-24	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312314
3052	Rear of building-37	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312377
3052	Rear of building-52	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312448
3052	Rear of building-03	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	3	1312399
3052	Rear of building-27	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312438
3052	Rear of building-26	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312318
3052	Roof	Poor	Packaged Unit (RTU), 3 Ton	1	1	1312423
3052	Roof	Poor	Packaged Unit (RTU), 3 Ton	1	1	1312340
3052	Ground level	Poor	Packaged Unit (RTU), 20 Ton	1	1	1312522
03052	Rear of building-45	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	3	1312568
3052	Rear of building-22	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312542
3052	Rear of building-28	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312392
3052	Rear of building-51	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312331
3052	Rear of building-38	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312444
3052	Rear of building-50	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312509
3052	Roof	Poor	Packaged Unit (RTU), 3 Ton	1	1	1312382
3052	Rear of building-34	Fair	Heat Pump, Wall-Mounted, 3.5 Ton	1	10	1312334
3052	Roof	Fair	Packaged Unit (RTU), 4 Ton	1	3	1312411
lectrical						
5012	Building interior	Fair	Distribution Panel, 120/208 V, 225 Amp	1	3	1312279
5012	Site	Poor	Secondary Transformer, Dry, 30 kVA	1	1	1312513
5012	Building interior	Fair	Distribution Panel, 120/208 V, 225 Amp	1	13	1312538

JF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
05012	Building exterior	Fair	Distribution Panel, 120/240 V, 400 Amp	1	10	1312298
05012	Site	Fair	Building/Main Switchboard, 120/208 V, 1,200 Amp	<u>.</u> 1	26	1312551
05012	Electrical room	Fair	Secondary Transformer, Dry, 30 kVA	<u>.</u> 1	14	1312557
05012	Building interior	Fair	Main Distribution Panel, 277/480 V, 225 Amp	 1	8	1312281
05012	Site	Poor	Secondary Transformer, Dry, 30 kVA	 1	1	1312561
05012	Utility closet	Fair	Secondary Transformer, Dry, 30 kVA	 1	16	1312368
05012	Electrical room	Fair	Secondary Transformer, Dry, 10 kVA	1	8	1312450
05012	Utility closet	Fair	Secondary Transformer, Dry, 30 kVA	1	13	1312560
05012	Electrical room	Fair	Distribution Panel, 120/208 V, 250 Amp	1	13	1312454
05012	Electrical room	Fair	Switchboard, 120/208 V, 500 Amp	 1	3	1312304
05012	Electrical room	Fair	Building/Main Switchboard, 277/480 V, 600 Amp	1	3	1312458
05012	Site	Fair	Secondary Transformer, Dry, 30 kVA	1	12	1312333
05019	Throughout	Fair	Full Electrical System Upgrade, Low Density/Complexity	55,066 SF	18	1313425
05022	Building exterior	Fair	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	4	10	1312473
05022	Building exterior- New restroom	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	3	17	1312447
05022	Building exterior	Fair	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	4	10	1312437
05022	Building exterior	Fair	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	3	13	1312434
05022	Building exterior	Fair	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	6	8	1312315
)5022	Building exterior	Fair	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	3	12	1312565
05022	Building exterior	Fair	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	2	8	1312495
05022	Building exterior	Fair	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	4	10	1312478
05022	Building exterior	Fair	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	2	10	1312424
05029	Throughout	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	55,066 SF	10	1313426
ire Alarm & Co						
05032	Throughout	Fair	Public Address/Announcement (PA) System, Facility Wide	55,066 SF	3	1313428
5037	Throughout	Poor	Fire Alarm System, Standard Addressable, Install	55,066 SF	2	1313424
5037	Data room	Fair	Fire Alarm Control Panel, Addressable	1	8	1312295
05038	Throughout	Fair	Security/Surveillance System, Cameras and CCTV, Install	55,066 SF	3	1312555
Equipment/Spec	cial					
1023	Stage	Fair	Stage Curtain, Medium Weight Velour, Flameproof (per SF)	340 SF	7	1312449
1028	Front office	Fair	Defibrillator (AED), Cabinet Mounted	1	5	1312300
1093	Kitchen	Fair	Commercial Kitchen, Refrigerator, 2-Door Reach-In	1	7	1312517
1093	Kitchen	Fair	Commercial Kitchen, Freezer, 2-Door Reach-In	1	8	1312395
1093	Kitchen	Fair	Commercial Kitchen, Refrigerator, 2-Door Reach-In	1	7	1312472
1093	Kitchen	Fair	Commercial Kitchen, Refrigerator, 2-Door Reach-In	1	7	1312332
1093	Kitchen	Fair	Commercial Kitchen, Refrigerator, 1-Door Reach-In	1	7	1312470
1093	Kitchen	Fair	Commercial Kitchen, Food Warmer	1	8	1312539
1093	Kitchen	Fair	Commercial Kitchen, Exhaust Hood, 8 to 10 LF	1	5	1312499
1093	Kitchen	Fair	Commercial Kitchen, Convection Oven, Double	1	5	1312540
1093	Kitchen	Fair	Commercial Kitchen, Freezer, 2-Door Reach-In	1	8	1312378
1093	Kitchen	Fair	Commercial Kitchen, Refrigerator, 1-Door Reach-In	1	7	1312307

NA

Z105X

Main entrance

Component Co	ondition Report			Draft - For D	/ISGUSSIOI	n Purpose
UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
≣1093	Kitchen	Fair	Commercial Kitchen, Food Warmer	1	8	1312476
2012	Throughout	Fair	Kitchen Cabinetry, Stock Hardwood	48 LF	10	1312308
2012	Throughout	Fair	Kitchen Cabinetry, Stock Hardwood	48 LF	10	1312431
E2012	Throughout	Fair	Kitchen Cabinetry, Stock Hardwood	36 LF	8	1312345
E2012	Throughout	Fair	Kitchen Cabinetry, Stock Hardwood	72 LF	10	1312426
E2012	Throughout	Fair	Kitchen Cabinetry, Stock Hardwood	34 LF	8	1312421
E2012	Throughout	Fair	Kitchen Cabinetry, Stock Hardwood	22 LF	10	1312457
E2012	Throughout	Fair	Kitchen Cabinetry, Stock Hardwood	60 LF	10	1312346
Pavement						
G2022	Parking lot	Fair	Parking Lots, Asphalt Pavement, Mill & Overlay	59,000 SF	8	1312526
G2022	Parking lot	Poor	Parking Lots, Asphalt Pavement, Cut & Patch	2,500 SF	0	1312321
G2022	Parking lot	Fair	Parking Lots, Asphalt Pavement, Seal & Stripe	59,000 SF	3	1312328
G2031	Sidewalk	Fair	Pedestrian Pavement, Sidewalk, Concrete Large Areas	15,500 SF	26	1312563
G2031	Sidewalk	Poor	Pedestrian Pavement, Sidewalk, Concrete Sections/Small Areas, Repair	240 SF	2	1312451
Site Developmen	nt					
G2041	Site	Fair	Fences & Gates, Wrought Iron, 6' High	320 LF	26	1312559
G2042	Site-adjacent to lunch shelter	Good	Retaining Wall, Cast-in-place Concrete (per SF Face)	150 SF	42	1312406
G2044	Building exterior	Fair	Signage, Property, Monument/Pylon	1	10	1312467
G2047	Playground	Fair	Play Structure, Small	1	14	1312518
G2047	Playground	Fair	Play Structure, Small	1	13	1312464
G2047	Playground	Excellent	Play Surfaces & Sports Courts, Poured-in-place Rubber	3,500 SF	20	1312427
G2047	Playground	Fair	Play Surfaces & Sports Courts, Asphalt, Seal & Stripe	34,000 SF	3	1312524
G2047	Playground	Fair	Play Surfaces & Sports Courts, Wood Chips, 3" Depth	1,800 SF	15	1312352
G2047	Playground	Fair	Sports Apparatus, Basketball Backstop	2	11	1312536
G2047	Playground	Excellent	Play Structure, Small	1	20	1312274
G2047	Playground	Fair	Play Surfaces & Sports Courts, Asphalt, Mill & Overlay	34,000 SF	8	1312493
G2049	Site	Fair	Shed, Wooden Framed, Asphalt Shingles	80 SF	18	1312276
Landscaping						
G2057	Site	Fair	Irrigation System, Replace/Install	155,000 SF	13	1312269
Follow-up Studie	es					
P000X	Throughout campus	NA	Engineer, Civil, Site/Storm Drainage, Evaluate/Report		0	1313439

ADA, Miscellaneous, Signage, Directional, Wall-Mounted, Install

4

0

1314276

Appendix D: ADA Abbreviated Checklist

	EMG ABREVIATE	O ADA	CHEC	KLIST	
	BUILDING HISTORY	YES	NO	N/A	COMMENTS
1.	Has the management previously completed an ADA review?		✓		
2.	Have any ADA improvements been made to the property?		✓		
3.	Does a Barrier Removal Plan exist for the property?		✓		
4.	Has the Barrier Removal Plan been reviewed/approved by an arms-length third party such as an engineering firm, architectural firm, building department, other agencies, etc.?		✓		
5.	Has building ownership or management received any ADA related complaints that have not been resolved?		✓		
6.	Is any litigation pending related to ADA issues?				
	PARKING	YES	NO	N/A	COMMENTS
1.	Are there sufficient parking spaces with respect to the total number of reported spaces?	✓			
2.	Are there sufficient van-accessible parking spaces available (96" wide/ 96" aisle for van)?	✓			
3.	Are accessible spaces marked with the International Symbol of Accessibility? Are there signs reading "Van Accessible" at van spaces?	✓			
4.	Is there at least one accessible route provided within the boundary of the site from public transportation stops, accessible parking spaces, passenger loading zones, if provided, and public streets and sidewalks?	✓			
5.	Do curbs on the accessible route have depressed, ramped curb cuts at drives, paths, and drop-offs?	✓			
6.	Does signage exist directing you to accessible parking and an accessible building entrance?		✓		
	RAMPS	YES	NO	N/A	COMMENTS
1.	If there is a ramp from parking to an accessible building entrance, does it meet slope requirements? (1:12)	✓			
2.	Are ramps longer than 6 ft complete with railings on both sides?	✓			
3.	Is the width between railings at least 36 inches?	✓			
4.	Is there a level landing for every 30 ft horizontal length of ramp, at the top and at the bottom of ramps and switchbacks?	✓			
	ENTRANCES/EXITS	YES	NO	N/A	COMMENTS
1.	Is the main accessible entrance doorway at least 32 inches wide?	✓			
2.	If the main entrance is inaccessible, are there alternate accessible entrances?	✓			
3.	Can the alternate accessible entrance be used independently?	✓			
4.	Is the door hardware easy to operate (lever/push type hardware, no twisting required, and not higher than 48 inches above the floor)?	✓			
5.	Are main entry doors other than revolving door available?	✓			
6.	If there are two main doors in series, is the minimum space between the doors 48 inches plus the width of any door swinging into the space?	✓			

	EMG ABREVIATED	ADA	CHEC	KLIST	
	PATHS OF TRAVEL	YES	NO	N/A	COMMENTS
1.	Is the main path of travel free of obstruction and wide enough for a wheelchair (at least 36 inches wide)?	✓			
2.	Does a visual scan of the main path reveal any obstacles (phones, fountains, etc.) that protrude more than 4 inches into walkways or corridors?	✓			
3.	Are floor surfaces firm, stable, and slip resistant (carpets wheelchair friendly)?	✓			
4.	Is at least one wheelchair-accessible public telephone available?			✓	
5.	Are wheelchair-accessible facilities (toilet rooms, exits, etc.) identified with signage?	✓			
6.	Is there a path of travel that does not require the use of stairs?	✓			
7.	If audible fire alarms are present, are visual alarms (strobe light alarms) also installed in all common areas?	✓			
	ELEVATORS	YES	NO	N/A	COMMENTS
	Do the call buttons have visual signals to indicate when a call is registered and answered?			✓	
2.	Are there visual and audible signals inside cars indicating floor change?			✓	
3.	Are there standard raised and Braille marking on both jambs of each host way entrance?			✓	
1.	Do elevator doors have a reopening device that will stop and reopen a car door if an object or a person obstructs the door?			✓	
5.	Do elevator lobbies have visual and audible indicators of car arrival?			✓	
3 .	Does the elevator interior provide sufficient wheelchair turning area (51" x 68")?			✓	
7 .	Are elevator controls low enough to be reached from a wheelchair (48 inches front approach/54 inches side approach)?			✓	
3.	Are elevator control buttons designated by Braille and by raised standard alphabet characters (mounted to the left of the button)?			✓	
9.	If a two-way emergency communication system is provided within the elevator cab, is it usable without voice communication?			✓	
	RESTROOMS	YES	NO	N/A	COMMENTS
	Are common area public restrooms located on an accessible route?	✓			
	Are pull handles push/pull or lever type?	✓			
	Are there audible and visual fire alarm devices in the toilet rooms?	✓			
	Are corridor access doors wheelchair-accessible (at least 32 inches wide)?	✓			
i.	Are public restrooms large enough to accommodate a wheelchair turnaround (60" turning diameter)?	✓			
3.	In unisex toilet rooms, are there safety alarms with pull cords?	✓			
	Are stall doors wheelchair accessible (at least 32" wide)?	✓			

	EMG ABREVIATED) ADA	CHEC	KLIST	
	RESTROOMS	YES	NO	N/A	COMMENTS
8.	Are grab bars provided in toilet stalls?	✓			
9.	Are sinks provided with clearance for a wheelchair to roll under (29" clearance)?	✓			
0.	Are sink handles operable with one hand without grasping, pinching or twisting?	✓			
1.	Are exposed pipes under sink sufficiently insulated against contact?	✓			
2.	Are soap dispensers, towel, etc. reachable (48" from floor for frontal approach, 54" for side approach)?	✓			
3.	Is the base of the mirror no more than 40" from the floor?	✓			
	POOLS	YES	NO	NA	COMMENTS
1	Are public access pools provided? If the answer is no, please disregard this section.			✓	
2	How many accessible access points are provided to each pool/spa?			✓	
3	Is at least one fixed lift or sloped entry to the pool provided?			✓	
	PLAY AREA	YES	NO	NA	COMMENTS
1	Has the play area been reviewed for accessibility? All public playgrounds are subject to ADAAG standards.		✓		
2	Are play structures accessible?		✓		
	EXERCISE EQUIPMENT	YES	NO	NA	COMMENTS
	Does there appear to be adequate clear floor space				

^{*}Based on visual observation only. The slope was not confirmed through measurement

Appendix E: Pre-Survey Questionnaire

EMG FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

Building / Facility Name:	Juniper
Name of person completing form:	Omar Renteria
Title / Association with property:	Maintenance Worker
Length of time associated w/ property:	1 year
Date Completed:	May 23 2019
Phone Number:	

Directions: Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses.

	DATA OVERVIEW		RE	ESPONSE					
1	Year/s constructed	1959							
2	Building size in SF	55066							
			Year	Additional Detail					
		Façade							
		Roof							
		Interiors							
3	Major Renovation/Rehabilitation	HVAC		Installation of newer EMS controls for HVAC					
		Electrical							
		Site Pavement							
		Accessibility							
	QUESTION		RI	ESPONSE					
4	List other significant capital improvements (focus on recent years; provide approximate date).	2019-Boost pump for 2019-Replacement	or water pressul of Kinder/Presc	re hool Playgrounds					
5	List any major capital expenditures planned/requested for the next few years. Have they been budgeted?	Replacement of eve	ery Ac Split unit	on all main buildings.					
6	Describe any on-going extremely problematic, historically chronic, or immediate facility needs.	xpenditures he next few budgeted? All structure building roof drains are rusted out and need to be replace New AC Package units for rooms 41,43 and 44							

Paging system: limited parts avail for head-end Camera system is analog and parts limited no clock sync system

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses. (**NA** indicates "*Not Applicable*", **Unk** indicates "*Unknown*")

	QUESTION			ONSE		COMMENTS
		Yes	No	Unk	NA	COMMENTO
7	Are there any problems with foundations or structures, like excessive settlement?	Х				Uneven concrete throughout exterior hallways of campus
8	Are there any wall, window, basement or roof leaks?	х				Roof drains are not working in all the building, relos rooms need new pvc roofs
9	Has any part of the facility ever contained visible suspect mold growth, or have there been any indoor air quality or mold related complaints from occupants?	X				Room 51
10	Are your elevators unreliable, with frequent service calls?				x	
11	Are there any plumbing leaks, water pressure, or clogging/back-up problems?		X			
12	Have there been any leaks or pressure problems with natural gas, HVAC supply/return lines, or steam service?			х		
13	Are any areas of the facility inadequately heated, cooled or ventilated? Any poorly insulated areas?	х				Recommend new AC units for rooms 3,7,45,46
14	Is the electrical service outdated, undersized, or otherwise problematic?	Х				Multiple service meters, Old building switchgear, Old underground wiring distribution (past shorting problems). Many overloaded circuits throughout main buildings.
15	Are there any problems or inadequacies with exterior lighting?	Х				No exterior parking lot lighting, campus lights scheduled to be upgraded to LED
16	Is site/parking drainage inadequate, with excessive ponding or other problems?			Х		
17	Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified above?	X				Service road storm water drainage
18	ADA: Has an accessibility study been performed at the site? If so, indicate when.			X		
19	ADA: If a study has occurred, have the associated recommendations been addressed? In full or in part?			X		

ADA: Have there been regular complaints about accessibility issues, or associated previous or pending litigation?	X	
---	---	--

Appendix F: Replacement Reserves

7/18/2019

ation Name	Uniformat Code	Location Description	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quant	ityOilit	Unit Cost	* Subtotal	2019	2020	2021 2	022 2023 2024 2025 2026 2027 2028 2	2029 203	30 2031	2032 20	033 203	4 2035 2	2036 2037	2038 203	39 Re
per Elementary School	C1023	Throughout	1313423 Door Hardware System, School (per Door), Replace	30	15	15	140	EA	\$436.4	0 \$61,09	6							\$61,096	6			
r Elementary School	D2029	Throughout	1313427 Plumbing System, Supply & Sanitary, Low Density (excl fixtures), Replace	40	22	18	5506	6 SF	\$5.4	6 \$300,38	5									\$300,385		
Elementary School	D2042	Throughout	1313441 Roof Drain, 2", Replace	40	38	2	90	EA	\$702.6	60 \$63,23	4		\$63,234									
Elementary School	D5019	Throughout	1313425 Full Electrical System Upgrade, Low Density/Complexity, Replace	40	22	18	5506	6 SF	\$14.1	8 \$781,00	1									\$781,001		_
Elementary School	D5029	Throughout	1313426 Lighting System, Interior, Medium Density & Standard Fixtures, Replace	20	10	10	5506	_		3 \$480,61				\$480,	616							+
r Elementary School	D5032		1313428 Public Address/Announcement (PA) System, Facility Wide, Replace	20	17	3	5506			0 \$99,12			\$99,		0.10						_	+
•		Throughout																-				+
r Elementary School	D5037	Throughout	1313424 Fire Alarm System, Standard Addressable, Install	20	18	2	5506		-	\$6 \$240,30			\$240,308									+
er Elementary School	D5038	Throughout	1312555 Security/Surveillance System, Cameras and CCTV, Install	15	12	3	5506			6 \$300,38			\$300,	885						\$300,385		4
er Elementary School	P000X	Throughout campus	1313439 Engineer, Civil, Site/Storm Drainage, Evaluate/Report	0	0	0	1	EA	\$7,637.0	90 \$7,63	7 \$7,637											
er Elementary School / Building 4	1-44 B2011	Building exterior	1312465 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	5	5	4000) SF	\$3.2	\$13,09	2			\$13,092				\$13,092	2			
er Elementary School / Building 4	1-44 B2021	Building exterior	1312416 Window, Wood 24 SF, 1-2 Stories, Replace	30	16	14	16	EA	\$1,309.2	20,94	7						\$20,9	47				
er Elementary School / Building 4	1-44 B2032	Building exterior	1312320 Exterior Door, Wood Solid-Core, Replace	25	15	10	4	EA	\$763.7	0 \$3,05	5			\$3,	055							
er Elementary School / Building 4	1-44 B3011	Roof	1312270 Roof, Single-Ply TPO/PVC Membrane, Replace	20	12	8	3400) SF	\$18.5	5 \$63,06	0			\$63,060								
er Elementary School / Building 4	1-44 C1021	Building interior	1312463 Interior Door, Wood Solid-Core, Replace	40	22	18	8	EA	\$763.7	0 \$6,11	0									\$6,110		\top
er Elementary School / Building 4		Throughout	1312357 Interior Wall Finish, any surface, Prep & Paint	10	5	5	4000) SF	\$1.6	64 \$6,54	6			\$6,546				\$6,546	6			+
er Elementary School / Building 4		Restroom	1312442 Interior Floor Finish, Vinyl Sheeting, Replace	15	10	5	120			34 \$91				\$916				+			\$916	16
						+ -	_	_														-
er Elementary School / Building 4		Throughout	1312312 Interior Floor Finish, Vinyl Tile (VCT), Replace	15	10	5	240			6 \$1,30		000 :=:		\$1,309							\$1,309	.9
er Elementary School / Building 4		Throughout	1312343 Interior Floor Finish, Carpet Commercial Standard, Replace	10	9	1	2500			8 \$20,45		\$20,456			\$20,45							4
er Elementary School / Building 4		Throughout	1312543 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	14	11	2500			\$9,54					\$9,54	16						4
er Elementary School / Building 4	1-44 D2011	Restroom	1312415 Toilet, Tankless (Water Closet), Replace	30	16	14	4	EA	\$1,013.5	\$4,05	4						\$4,0	54				\perp
er Elementary School / Building 4	1-44 D2014	Throughout	1312291 Sink/Lavatory, Vanity Top, Stainless Steel, Replace	30	16	14	4	EA	\$1,309.2	20 \$5,23	7						\$5,2	37				
er Elementary School / Building 4	1-44 D2014	Restroom	1312535 Sink/Lavatory, Wall-Hung, Vitreous China, Replace	30	16	14	2	EA	\$1,636.5	\$3,27	3						\$3,2	73				
er Elementary School / Building 4	1-44 D2014	Custodian closet	1312554 Service Sink, Wall-Hung, Replace	35	20	15	1	EA	\$1,527.4	0 \$1,52	7							\$1,527	7			
er Elementary School / Building 4	1-44 D2018	Building exterior	1312301 Drinking Fountain, Outside/Site Style, Replace	15	9	6	1	EA	\$3,927.6	0 \$3,92	8			\$3,928								T
er Elementary School / Building 4	1-44 D2023	Custodian closet	1312441 Water Heater, Electric, Residential, 15 GAL, Replace	15	8	7	1	EA	\$600.0	5 \$60	0			\$600								+
er Elementary School / Building 4		Roof	1312278 Exhaust Fan, Roof or Wall Mounted, 50 to 500 CFM, Replace	20	12	8	1	EA	-	-				\$1,309								+
er Elementary School / Building 4		Roof	1312347 Exhaust Fan, Roof or Wall Mounted, 50 to 500 CFM, Replace	20	12	8	1	EA						\$1,309							-	+
			· ·			-	· ·					DO 400		φ1,309				-				+
er Elementary School / Building 4		Roof	1312423 Packaged Unit (RTU), 3 Ton, Replace	20	19	1	1	EA		50 \$8,18		\$8,183										+
er Elementary School / Building 4		Roof	1312340 Packaged Unit (RTU), 3 Ton, Replace	20	19	1	1	EA		50 \$8,18		\$8,183										4
er Elementary School / Building 4	1-44 D3052	Roof	1312382 Packaged Unit (RTU), 3 Ton, Replace	20	19	1	1	EA	\$8,182.5	\$8,18	3	\$8,183										_
er Elementary School / Building 4	1-44 D3052	Roof	1312370 Packaged Unit (RTU), 3 Ton, Replace	20	2	18	1	EA	\$8,182.5	\$8,18	3									\$8,183		
er Elementary School / Building 4	1-44 D5012	Building interior	1312279 Distribution Panel, 120/208 V, 225 Amp, Replace	30	27	3	1	EA	\$2,182.0	00 \$2,18	2		\$2,	82								
er Elementary School / Building 4	1-44 D5022	Building exterior	1312495 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Repla	ce 20	12	8	2	EA	\$229.1	11 \$45	8			\$458								
er Elementary School / Building 4	1-44 E2012	Throughout	1312431 Kitchen Cabinetry, Stock Hardwood, Replace	20	10	10	48	LF	\$327.3	\$15,71	0			\$15,	710							
er Elementary School / Building A	B2011	Building exterior	1312520 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	5	5	8500) SF	\$3.2	27 \$27,82	1			\$27,821				\$27,82	1			\top
er Elementary School / Building A	B2021	Building Exterior	1312488 Window, Wood 12 SF, 1-2 Stories, Replace	30	16	14	12	EA	\$872.8	80 \$10,47	4						\$10,4	.74				+
er Elementary School / Building A		Building Exterior	1312389 Exterior Door, Wood Solid-Core, Replace	25	14	11	8			0 \$6,11					\$6,11	10	4.0,1	+			-	+
			· · · · · · · · · · · · · · · · · · ·		_	14									ΨΟ,ΤΙ	10	645.0	104				+
er Elementary School / Building A		Roof	1312311 Roof, Asphalt Shingle 30-Year, Replace	30	16	_				00 \$45,90							\$45,9	J4			_	+
er Elementary School / Building A		Building interior	1312496 Interior Door, Wood Solid-Core, Replace	40	22	18	8	_		0 \$6,11										\$6,110		+
er Elementary School / Building A	C1031	Common area restrooms	1312319 Toilet Partitions, Metal, Replace	20	10	10	2	EA	\$927.3	\$1,85	5			\$1,	855							_
er Elementary School / Building A	C3012	Throughout	1312386 Interior Wall Finish, any surface, Prep & Paint	10	5	5	7500) SF	\$1.6	\$12,27	4			\$12,274				\$12,274	4			_
er Elementary School / Building A	C3012	Common area restrooms	1312396 Interior Wall Finish, Ceramic Tile, Replace	40	22	18	500	SF	\$19.6	\$9,81	9									\$9,819		
er Elementary School / Building A	C3024	Throughout	1312541 Interior Floor Finish, Linoleum, Replace	15	7	8	600	SF	\$3.8	\$2,29	1			\$2,291								
er Elementary School / Building A	C3024	Common area restrooms	1312545 Interior Floor Finish, Ceramic Tile, Replace	40	22	18	350	SF	\$19.6	\$6,87	3									\$6,873		
er Elementary School / Building A	C3025	Throughout	1312335 Interior Floor Finish, Carpet Commercial Standard, Replace	10	4	6	2800) SF	\$8.1	8 \$22,91	1			\$22,911					\$22,911			T
er Elementary School / Building A	C3031	Throughout	1312430 Interior Ceiling Finish, any flat surface, Prep & Paint	10	5	5	400	SF	\$2.1	8 \$87	3			\$873				\$873	3			\top
r Elementary School / Building A		Throughout	1312523 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	13	12	4500			32 \$17,18						\$17,183						+
						_		_								ψ17,100		\$2.04	1		-	+
Elementary School / Building A		Common area restrooms	1312324 Toilet, Tankless (Water Closet), Replace	30	15	15	3								020			\$3,04	'			+
Elementary School / Building A		Throughout	1312326 Sink/Lavatory, Vanity Top, Stainless Steel, Replace	30	20	10	3			93,92				\$3,	928							+
Elementary School / Building A		Common area restrooms	1312273 Sink/Lavatory, Wall-Hung, Vitreous China, Replace	30	16	14	2			50 \$3,27							\$3,2	73				4
Elementary School / Building A	D2023	Custodian room	1312310 Water Heater, Gas, Residential, 50 GAL, Replace	15	8	7	1	EA	\$1,418.3	\$1,41	8			\$1,418								\perp
Elementary School / Building A	D3032	Roof	1312403 Condensing Unit/Heat Pump, Split System, 5 Ton, Replace	15	8	7	1	EA	\$7,746.1	0 \$7,74	6			\$7,746								
Elementary School / Building A	D3032	Roof	1312384 Ductless Split System, Single Zone, 2 Ton, Replace	15	7	8	1	EA	\$5,236.8	\$5,23	7			\$5,237								
r Elementary School / Building A	D3032	Roof	1312453 Condensing Unit/Heat Pump, Split System, 3 Ton, Replace	15	4	11	1	EA	\$4,364.0	0 \$4,36	4				\$4,36	64						T
r Elementary School / Building A	D3032	Roof	1312294 Condensing Unit/Heat Pump, Split System, 3 Ton, Replace	15	0	15	1	EA	\$4,364.0	0 \$4,36	4							\$4,364	4			\dagger
r Elementary School / Building A		Attic	1312365 Air Handler (AHU), Interior, 400 CFM, Replace	25	5	20	1		\$3,927.6									1			\$3,928	28
er Elementary School / Building A		Attic	1324927 Air Handler (AHU), Interior, 400 CFM, Replace	25	5	20	1		\$3,927.6												\$3,928	-
er Elementary School / Building A					-	_	_	_					\$43,	240				-			ψ3,920	+
	D5012	Electrical room	1312458 Building/Main Switchboard, 277/480 V, 600 Amp, Replace	40	37	3	1	. EΛ	E 42 640 0	0 \$43,64	111		E/13	Maria de la companya								

	Uniformat Code	Location Description	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quant	ityUnit	Unit Cost * Subtotal	2019 2020 2	2021 2022	2023 2024 2	025 2026 2027	2028 2029 203	0 2031 2	2032 2033 D	nft =FopDiscussi	on rurpose
er Elementary School / Building A	D5012	Building interior	1312538 Distribution Panel, 120/208 V, 225 Amp, Replace	30	17	13	1	EA	\$2,182.00 \$2,182						\$2,	,182		\$2
er Elementary School / Building A	D5022	Building exterior	1312434 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Re	eplace 20	7	13	3	EA	\$229.11 \$687						\$	\$687		:
er Elementary School / Building A	D5037	Data room	1312295 Fire Alarm Control Panel, Addressable, Replace	15	7	8	1	EA	A \$16,365.00 \$16,365				\$16,365					\$16
er Elementary School / Building A	E1028	Front office	1312300 Defibrillator (AED), Cabinet Mounted, Replace	10	5	5	1	EA	\$1,636.50 \$1,637			\$1,637				\$1,637		\$3
er Elementary School / Building A	E2012	Throughout	1312345 Kitchen Cabinetry, Stock Hardwood, Replace	20	12	8	36	LF	\$327.30 \$11,783				\$11,783					\$11
er Elementary School / Building B	B2011	Building Exterior	1312533 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	5	5	8500) SF	\$3.27 \$27,821			\$27,821				\$27,821		\$55
er Elementary School / Building B	B2021	Building Exterior	1312512 Window, Wood 12 SF, 1-2 Stories, Replace	30	16	14	14	EA	A \$872.80 \$12,219							\$12,219		\$12
er Elementary School / Building B	B2032	Building Exterior	1312485 Exterior Door, Wood Solid-Core, Replace	25	14	11	12	EA	A \$763.70 \$9,164					\$9,164	4			\$9
er Elementary School / Building B	B3011	Roof	1312302 Roof, Asphalt Shingle 30-Year, Replace	30	14	16	8300) SF	\$6.00 \$49,804								\$49,804	\$49
er Elementary School / Building B	C1021	Throughout	1312387 Interior Door, Wood Solid-Core, Replace	40	22	18	8	EA	\$763.70 \$6,110								\$6,110	\$6
er Elementary School / Building B	C3012	Throughout	1312404 Interior Wall Finish, any surface, Prep & Paint	10	5	5	8500) SF	\$1.64 \$13,910			\$13,910				\$13,910		\$27
per Elementary School / Building B	C3012	Restroom	1312481 Interior Wall Finish, Ceramic Tile, Replace	40	22	18	220	SF	\$19.64 \$4,320								\$4,320	\$4
er Elementary School / Building B	C3024	Throughout	1312327 Interior Floor Finish, Vinyl Tile (VCT), Replace	15	9	6	5800) SF	\$5.46 \$31,639			\$31,	639					\$31
er Elementary School / Building B	C3024	Restroom	1312572 Interior Floor Finish, Ceramic Tile, Replace	40	22	18	220	SF	\$19.64 \$4,320								\$4,320	\$4
per Elementary School / Building B	C3031	Throughout	1312537 Interior Ceiling Finish, any flat surface, Prep & Paint	10	5	5	500	SF	\$2.18 \$1,091			\$1,091				\$1,091		\$2
per Elementary School / Building B	C3032	Throughout	1312337 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	12	13	5800) SF	\$3.82 \$22,147						\$22,	.,147		\$22
, , , , , , , , , , , , , , , , , , , ,	D1013	Stage	1312339 Wheelchair Lift, 5' Rise, Renovate	25	12	13	_	EA							\$20,			\$20
, ,	D2011	Restroom	1312503 Toilet, Tankless (Water Closet), Replace	30	14	16	3	E/							1.10)		\$3,041	\$3
, ,	D2014	Janitor room	1312486 Service Sink, Wall-Hung, Replace	35	25	10	2	E/						\$3,055				\$3
	D2014	Restroom	1312468 Sink/Lavatory, Wall-Hung, Vitreous China, Replace	30	16	14	3	E/								\$4,910		\$4
· · · · · · · · · · · · · · · · · · ·	D2014	Kitchen	1312407 Commercial Kitchen Sink, Stainless Steel, 1-Bowl, Replace	30	14	16	1	E/								- 77-1-	\$1,746	\$1
•	D2014	Kitchen	1312277 Commercial Kitchen Sink, Stainless Steel, 3-Bowl, Replace	30	14	16		E/									\$2,728	\$2
, , , , , , , , , , , , , , , , , , , ,	D2018	Building exterior	1312550 Drinking Fountain, Outside/Site Style, Replace	15	7	8	_						\$3,928					\$3
, ,	D2023	Janitor room	1312534 Water Heater, Gas, Residential, 75 GAL, Replace	15	4	11		_					\$0,020	\$2,073	3			\$2
	D3052	Ground level	1312522 Packaged Unit (RTU), 20 Ton, Replace	20	19	1	1	E/		\$43,640				Ψ2,070				\$43
-	D3052	Roof	1312325 Packaged Unit (RTU), 7.5 Ton, Replace	20	17	3		E/		\$70,070	\$16,365							\$16
, ,	D3052	Roof	1312411 Packaged Unit (RTU), 4 Ton, Replace	20	17	3	_	E/			\$9,819							\$16
•	D5052	Electrical room	1312451 Distribution Panel, 120/208 V, 250 Amp, Replace	30	17	13		E/			ψ3,013				60	.,182		\$2
	D5012	Building exterior	1312494 Distribution Panet, 120/206 V, 250 Amp, Replace 1312565 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Re		ο ο	12	3	EA							\$687	., 102		\$2
	E1023	-		20 15	0	7	340						\$5,312		ΨΟΟΙ			\$5
	E1023	Stage Kitchen	1312449 Stage Curtain, Medium Weight Velour, Flameproof (per SF), Replace	15	10	5	340	E/				\$4,910	φυ,υ ΙΖ					\$4,910 \$9
, , , , , , , , , , , , , , , , , , , ,			1312499 Commercial Kitchen, Exhaust Hood, 8 to 10 LF, Replace	15	5	-										£40.005		
, ,	E1093	Kitchen	1312540 Commercial Kitchen, Convection Oven, Double, Replace			5	_					\$10,365	¢5 040			\$10,365		\$20
er Elementary School / Building B	E1093	Kitchen	1312517 Commercial Kitchen, Refrigerator, 2-Door Reach-In, Replace	15	8	- '	1						\$5,019					\$0
er Elementary School / Building B	E1093	Kitchen	1312472 Commercial Kitchen, Refrigerator, 2-Door Reach-In, Replace	15	8	7 -	1	_					\$5,019					\$5
er Elementary School / Building B	E1093	Kitchen	1312332 Commercial Kitchen, Refrigerator, 2-Door Reach-In, Replace	15	8	7 -	1	E/					\$5,019					\$5
, ,	E1093	Kitchen	1312470 Commercial Kitchen, Refrigerator, 1-Door Reach-In, Replace	15	8								\$2,946					\$2
· · · · · · · · · · · · · · · · · · ·	E1093	Kitchen	1312307 Commercial Kitchen, Refrigerator, 1-Door Reach-In, Replace	15	8	7	1						\$2,946					\$2
	E1093	Kitchen	1312395 Commercial Kitchen, Freezer, 2-Door Reach-In, Replace	15	7	8	1	E/					\$5,564					\$5
· · · · · · · · · · · · · · · · · · ·	E1093	Kitchen	1312539 Commercial Kitchen, Food Warmer, Replace	15	7	8	_	_	\$1,854.70 \$1,855				\$1,855					\$1
•	E1093	Kitchen	1312378 Commercial Kitchen, Freezer, 2-Door Reach-In, Replace	15	7	8	1						\$5,564					\$5
, , , , , , , , , , , , , , , , , , ,	E1093	Kitchen	1312476 Commercial Kitchen, Food Warmer, Replace	15	7	8							\$1,855					\$1
, ,	E2012	Throughout	1312308 Kitchen Cabinetry, Stock Hardwood, Replace	20	10	10								\$15,710				\$15
	G2044	Building exterior	1312467 Signage, Property, Monument/Pylon, Replace	20	10	10			A \$10,364.50 \$10,365					\$10,365				\$10
, ,	B2011	Building Exterior	1312527 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	5	5		_				\$27,821				\$27,821		\$55
· · · · · · · · · · · · · · · · · · ·	B2021	Building Exterior	1312323 Window, Wood 12 SF, 1-2 Stories, Replace	30	16	14		_								\$13,092		\$13
· · · · · · · · · · · · · · · · · · ·	B2032	Building Exterior	1312504 Exterior Door, Steel, Replace	40	22												\$6,546	\$€
, , , , , , , , , , , , , , , , , , ,	B3011	Roof	1312548 Roof, Asphalt Shingle 30-Year, Replace	30	16	14										\$49,204		\$49
er Elementary School / Building C		Throughout	1312341 Interior Door, Wood Solid-Core, Replace	40	22		6	EA									\$4,582	\$4
er Elementary School / Building C		Common area restrooms	1312475 Toilet Partitions, Metal, Replace	20	10	10								\$3,709				\$3
er Elementary School / Building C	C3012	Throughout	1312393 Interior Wall Finish, any surface, Prep & Paint	10	5	5						\$13,910				\$13,910		\$27
er Elementary School / Building C	C3012	Common area restrooms	1312303 Interior Wall Finish, Ceramic Tile, Replace	40	22	18	550	SF	\$19.64 \$10,801								\$10,801	\$10
er Elementary School / Building C	C3024	Common area restrooms	1312350 Interior Floor Finish, Ceramic Tile, Replace	40	22	18	360	SF	\$19.64 \$7,070								\$7,070	\$7
r Elementary School / Building C	C3025	Throughout	1312502 Interior Floor Finish, Carpet Commercial Standard, Replace	10	5	5	6000) SF	\$8.18 \$49,095			\$49,095				\$49,095		\$98
Elementary School / Building C	C3031	Common area restrooms	1312552 Interior Ceiling Finish, any flat surface, Prep & Paint	10	5	5	460	SF	\$2.18 \$1,004			\$1,004				\$1,004		\$
r Elementary School / Building C	C3032	Throughout	1312361 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	13	12	5800) SF	\$3.82 \$22,147						\$22,147			\$2
Elementary School / Building C	D2011	Restroom	1312371 Toilet, Tankless (Water Closet), Replace	30	16	14	6	EA	\$1,013.54 \$6,081							\$6,081		\$
r Elementary School / Building C	D2012	Common area restrooms	1312507 Urinal, Standard, Replace	30	16	14	2	EA	\$1,200.10 \$2,400							\$2,400		\$
er Elementary School / Building C	D2014	Throughout	1312436 Sink/Lavatory, Vanity Top, Solid Surface or Vitreous China, Replace	30	24	6	5	EA	\$1,200.10 \$6,001			\$6,0	001					\$
r Elementary School / Building C	D2014	Custodian closet	1312553 Service Sink, Wall-Hung, Replace	35	22	13	1	EA	\$1,527.40 \$1,527						\$1,	,527		\$
er Elementary School / Building C	D2014	Common area restrooms	1312283 Sink/Lavatory, Wall-Hung, Vitreous China, Replace	30	16	14	6	EA	\$1,636.50 \$9,819							\$9,819		\$:
er Elementary School / Building C	D2018	Building exterior	1312383 Drinking Fountain, Outside/Site Style, Replace	15	7	8	1	EA	A \$3,927.60 \$3,928				\$3,928					\$
er Elementary School / Building C	D2023	Janitor room	1312348 Water Heater, Electric, Residential, 30 GAL, Replace	15	7	8	1	EA	A \$981.90 \$982				\$982					
	D3032	Roof	1312354 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	1	14	_	E/								\$5,673		\$5
	D3032	Roof	1312272 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15			1											

cation Name	Uniformat Code	Location Description		Lifespan (EUL)	EAge	RUL	Quantity	/Unit	Unit Cost * Subtotal 2019 20	020 2021 2022	2023 2024 20	25 2026 2027 2	2028 2029 203	0 2031	2032 2033	forÐisæussion þ	wijaase
er Elementary School / Building C	D3032	Roof	1312342 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	1	14	1	EA	\$5,673.20 \$5,673						\$5,673		\$
er Elementary School / Building C	D3032	Roof	1312433 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	0	15	1	EA	\$5,673.20 \$5,673						\$5,673		\$
r Elementary School / Building C	D3032	Roof	1312482 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	0	15	1	EA	\$5,673.20 \$5,673						\$5,673		\$
er Elementary School / Building C	D5012	Electrical room	1312304 Switchboard, 120/208 V, 500 Amp, Replace	40	37	3	1	EA	\$43,640.00 \$43,640	\$43,640							\$4
er Elementary School / Building C	D5012	Building exterior	1312298 Distribution Panel, 120/240 V, 400 Amp, Replace	30	20	10	1	EA	\$6,000.50 \$6,001				\$6,001				\$
er Elementary School / Building C	D5012	Electrical room	1312557 Secondary Transformer, Dry, 30 kVA, Replace	30	16	14	1	EA	\$7,309.70 \$7,310						\$7,310		\$
· · · · · · · · · · · · · · · · · · ·	D5022	Building exterior	1312315 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	20	12	8	6	EA	\$229.11 \$1.375			\$1,375					\$
	B2011	-	1312385 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	12	5	8500	SF	\$3.27 \$27,821		\$27,821	Ψ1,070			\$27,821		\$5
		Building Exterior			- 10						φ21,021						
· · · · · · · · · · · · · · · · · · ·	B2021	Building Exterior	1312469 Window, Wood 24 SF, 1-2 Stories, Replace	30	16	14	18	EA	\$1,309.20 \$23,566						\$23,566		\$2
er Elementary School / Building D	B2032	Building Exterior	1312353 Exterior Door, Wood Solid-Core, Replace	25	14	11	6	EA	\$763.70 \$4,582				\$4,582	2			
per Elementary School / Building D	B3011	Roof	1312474 Roof, Asphalt Shingle 30-Year, Replace	30	16	14	8200	SF	\$6.00 \$49,204						\$49,204		\$4
per Elementary School / Building D	C1021	Building interior	1312452 Interior Door, Wood Solid-Core, Replace	40	22	18	6	EA	\$763.70 \$4,582							\$4,582	
er Elementary School / Building D	C3012	Throughout	1312317 Interior Wall Finish, any surface, Prep & Paint	10	5	5	8500	SF	\$1.64 \$13,910		\$13,910				\$13,910		\$2
per Elementary School / Building D	C3025	Throughout	1312420 Interior Floor Finish, Carpet Commercial Standard, Replace	10	5	5	5500	SF	\$8.18 \$45,004		\$45,004				\$45,004		\$9
per Elementary School / Building D	C3032	Throughout	1312290 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	12	13	5800	SF	\$3.82 \$22,147					\$2	22,147		\$2
per Elementary School / Building D	D2014	Throughout	1312418 Sink/Lavatory, Vanity Top, Stainless Steel, Replace	30	16	14	6	EA	\$1,309.20 \$7,855						\$7,855		\$
er Elementary School / Building D	D3032	Roof	1312514 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	1	14	1	EA	\$5,673.20 \$5,673						\$5,673		•
er Elementary School / Building D	D3032	Roof	1312379 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	1	14	1	EA	\$5,673.20 \$5,673						\$5,673		•
er Elementary School / Building D	D3032	Roof		15	,	15	1	EA	\$5,673.20 \$5,673						\$5,673		
			1312570 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace		0		1										
er Elementary School / Building D	D3032	Roof	1312394 Condensing Unit/Heat Pump4 Ton, Split System, 4 Ton, Replace	15	0	15	1	EA	\$5,673.20 \$5,673						\$5,673		
per Elementary School / Building D	D3032	Roof	1312484 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	0	15	1	EA	\$5,673.20 \$5,673						\$5,673		
per Elementary School / Building D	D3032	Roof	1312372 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	0	15	1	EA	\$5,673.20 \$5,673						\$5,673		
per Elementary School / Building D	D5012	Building interior	1312281 Main Distribution Panel, 277/480 V, 225 Amp, Replace	30	22	8	1	EA	\$3,273.00 \$3,273			\$3,273					
per Elementary School / Building D	D5022	Building exterior	1312478 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	20	10	10	4	EA	\$229.11 \$916				\$916				
er Elementary School / Building D	E2012	Throughout	1312346 Kitchen Cabinetry, Stock Hardwood, Replace	20	10	10	60	LF	\$327.30 \$19,638				\$19,638				\$
er Elementary School / Building E	B2011	Building Exterior	1312529 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	5	5	9500	SF	\$3.27 \$31,094		\$31,094				\$31,094		\$
er Elementary School / Building E	B2021	Building Exterior	1312374 Window, Wood 12 SF, 1-2 Stories, Replace	30	16	14	16	EA	\$872.80 \$13,965						\$13,965		\$
er Elementary School / Building E	B2032	Building Exterior	1312414 Exterior Door, Wood Solid-Core, Replace	25	13	12	10	EA	\$763.70 \$7,637					\$7,637			
er Elementary School / Building E	B3011	Roof	1312401 Roof, Asphalt Shingle 30-Year, Replace	30	18	12	7950	SF	\$6.00 \$47,704					\$47,704			\$
	C1021	Building interior	1312419 Interior Door, Wood Solid-Core, Replace	40	22	18	6	EA	\$763.70 \$4,582							\$4,582	.
		-	·				-						\$5.564			ψτ,συΔ	
er Elementary School / Building E	C1031	Common area restrooms	1312567 Toilet Partitions, Metal, Replace	20	10	10	6	EA	\$927.35 \$5,564				\$5,564				
er Elementary School / Building E	C3012	Throughout	1312501 Interior Wall Finish, any surface, Prep & Paint	10	5	5	9500	SF	\$1.64 \$15,547		\$15,547				\$15,547		
er Elementary School / Building E	C3012	Common area restrooms	1312489 Interior Wall Finish, Ceramic Tile, Replace	40	22	18	550	SF	\$19.64 \$10,801							\$10,801	
er Elementary School / Building E	C3024	Common area restrooms	1312400 Interior Floor Finish, Ceramic Tile, Replace	40	22	18	360	SF	\$19.64 \$7,070							\$7,070	
per Elementary School / Building E	C3025	Throughout	1312398 Interior Floor Finish, Carpet Commercial Standard, Replace	10	5	5	5500	SF	\$8.18 \$45,004		\$45,004				\$45,004		\$
er Elementary School / Building E	C3031	Throughout	1312532 Interior Ceiling Finish, any flat surface, Prep & Paint	10	5	5	800	SF	\$2.18 \$1,746		\$1,746				\$1,746		
per Elementary School / Building E	C3032	Throughout	1312531 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	13	12	5800	SF	\$3.82 \$22,147					\$22,147			\$:
per Elementary School / Building E	D2011	Common area restrooms	1312359 Toilet, Tankless (Water Closet), Replace	30	16	14	6	EA	\$1,013.54 \$6,081						\$6,081		
per Elementary School / Building E	D2012	Common area restrooms	1312305 Urinal, Standard, Replace	30	16	14	2	EA	\$1,200.10 \$2,400						\$2,400		
per Elementary School / Building E	D2014	Common area restrooms	1312491 Sink/Lavatory, Wall-Hung, Vitreous China, Replace	30	16	14	6	EA	\$1,636.50 \$9,819						\$9,819		
	D2014	Building interior	1312412 Sink/Lavatory, Vanity Top, Stainless Steel, Replace	30	16	14	4		\$1,309.20 \$5,237						\$5,237		
•		-			4		1						\$4,364		ψυ,201		
	D3032	Roof	1312322 Condensing Unit/Heat Pump, Split System, 3 Ton, Replace	15		11	· ·	EA	\$4,364.00 \$4,364								
er Elementary School / Building E	D3032	Roof	1312490 Condensing Unit/Heat Pump, Split System, 3.5 Ton, Replace	15	4	11	1	EA	\$5,018.60 \$5,019				\$5,019				
er Elementary School / Building E	D3032	Roof	1312280 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	3	12	1	EA	\$5,673.20 \$5,673					\$5,673			
er Elementary School / Building E	D3032	Roof	1312373 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	3	12	1	EA	\$5,673.20 \$5,673					\$5,673			
er Elementary School / Building E	D3032	Building E	1312546 Condensing Unit/Heat Pump, Split System, 3.5 Ton, Replace	15	1	14	1	EA	\$5,018.60 \$5,019						\$5,019		
er Elementary School / Building E	D3052	Roof	1312521 Packaged Unit (RTU), 7.5 Ton, Replace	20	1	19	1	EA	\$16,365.00 \$16,365							\$16,365	\$
er Elementary School / Building E	D5022	Building exterior	1312437 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	20	10	10	4	EA	\$229.11 \$916				\$916				
er Elementary School / Building E	E2012	Throughout	1312426 Kitchen Cabinetry, Stock Hardwood, Replace	20	10	10	72	LF	\$327.30 \$23,566				\$23,566				\$
er Elementary School / Building F	B2011	Building Exterior	1312285 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	5	5	6500	SF	\$3.27 \$21,275		\$21,275				\$21,275		\$
er Elementary School / Building F	B2021	Building Exterior	1312287 Window, Wood 12 SF, 1-2 Stories, Replace	30	16	14	8	EA	\$872.80 \$6,982						\$6,982		
Elementary School / Building F	B2032	Building Exterior	1312271 Exterior Door, Wood Solid-Core, Replace	25	12	13	7	EA	\$763.70 \$5,346					•	55,346		
	B3011	Roof			16	14	4900	SF	\$6.00 \$29,402					Φ.	\$29,402		
Elementary School / Building F			1312360 Roof, Asphalt Shingle 30-Year, Replace	30											Ψ ∠ 3, 1 0 ∠	60.004	
Elementary School / Building F	C1021	Building interior	1312409 Interior Door, Wood Solid-Core, Replace	40	22	18	3	EA	\$763.70 \$2,291							\$2,291	
Elementary School / Building F	C3012	Throughout	1312376 Interior Wall Finish, any surface, Prep & Paint	10	5	5	6500	SF	\$1.64 \$10,637		\$10,637				\$10,637		
r Elementary School / Building F	C3012	Restroom	1312413 Interior Wall Finish, Ceramic Tile, Replace	40	22	18	320	SF	\$19.64 \$6,284							\$6,284	
r Elementary School / Building F	C3024	Throughout	1312286 Interior Floor Finish, Vinyl Tile (VCT), Replace	15	7	8	280	SF	\$5.46 \$1,527			\$1,527					
r Elementary School / Building F	C3024	Restroom	1312446 Interior Floor Finish, Ceramic Tile, Replace	40	22	18	160	SF	\$19.64 \$3,142							\$3,142	
r Elementary School / Building F	C3025	Throughout	1312306 Interior Floor Finish, Carpet Commercial Standard, Replace	10	5	5	3100	SF	\$8.18 \$25,366		\$25,366				\$25,366		:
r Elementary School / Building F	C3031	Restroom	1312439 Interior Ceiling Finish, any flat surface, Prep & Paint	10	5	5	340	SF	\$2.18 \$742		\$742				\$742		
er Elementary School / Building F	C3032	Throughout	1312422 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	13	12	2800		\$3.82 \$10,692					\$10,692			\$
er Elementary School / Building F	D2011	Restroom	1312356 Toilet, Tankless (Water Closet), Replace	30	16	14	4	EA	\$1,013.54 \$4,054						\$4,054		
er Elementary School / Building F	D2014			30	16	14	3	EA							\$3,928		
	D2014	Throughout	1312480 Sink/Lavatory, Vanity Top, Stainless Steel, Replace	30	10	14	٥	EA	ψ1,000.20 φ3,320						ψυ,υ <u>ε</u> 0		

per Elementary School / Building F per Elementary School / Building G canaz per Elementary School / Building G	032 012 012 012 011 011 021 032 011 012 025 032	Roof Utility closet Building exterior Throughout Building Exterior Building Exterior Building Exterior Roof Throughout Throughout Throughout	1312296 Condensing Unit/Heat Pump, Split System, 5 Ton, Replace 1312288 Condensing Unit/Heat Pump, Split System, 5 Ton, Replace 1312368 Secondary Transformer, Dry, 30 kVA, Replace 1312424 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace 1312457 Kitchen Cabinetry, Stock Hardwood, Replace 1312455 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint 1312511 Window, Wood 24 SF, 1-2 Stories, Replace 1312505 Exterior Door, Wood Solid-Core, Replace 1312275 Roof, Asphalt Shingle 30-Year, Replace	20 10 30 25	1 1 14 10 10 5 16	14 14 16 10 10 5	1 1 1 2 22	EA EA EA	\$7,746. \$7,309.	.10 \$7,746 .10 \$7,746 .70 \$7,310						\$7,746 \$7,746	\$7,310	
per Elementary School / Building F per Elementary School / Building G	0112 0122 0112 0111 0111 0121 0111 0112 0125 0132 014	Utility closet Building exterior Throughout Building Exterior Building Exterior Building Exterior Roof Throughout Throughout Throughout	1312368 Secondary Transformer, Dry, 30 kVA, Replace 1312424 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace 1312457 Kitchen Cabinetry, Stock Hardwood, Replace 1312455 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint 1312511 Window, Wood 24 SF, 1-2 Stories, Replace 1312505 Exterior Door, Wood Solid-Core, Replace 1312275 Roof, Asphalt Shingle 30-Year, Replace	30 20 20 10 30 25	10 10 5 16	16 10 10 5	1 2 22	EA EA	\$7,309.	70 \$7,310						\$7,746	\$7,310	
er Elementary School / Building F E2012 er Elementary School / Building F E2012 er Elementary School / Building G B2021 er Elementary School / Building G B2021 er Elementary School / Building G B2032 er Elementary School / Building G B2032 er Elementary School / Building G C3012 er Elementary School / Building G C3025 er Elementary School / Building G C3032 er Elementary School / Building G D2014 er Elementary School / Building G D3032 er Elementary School / Building G D5012 er Elementary School / Building G D5012 er Elementary School / Building G D5012	022 011 011 011 021 032 011 012 025 032 014	Building exterior Throughout Building Exterior Building Exterior Building Exterior Roof Throughout Throughout Throughout	1312424 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace 1312457 Kitchen Cabinetry, Stock Hardwood, Replace 1312455 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint 1312511 Window, Wood 24 SF, 1-2 Stories, Replace 1312505 Exterior Door, Wood Solid-Core, Replace 1312275 Roof, Asphalt Shingle 30-Year, Replace	20 20 10 30 25	10 10 5 16	10 10 5	2 22	EA									\$7,310	
er Elementary School / Building F Er Elementary School / Building F Er Elementary School / Building G	0222 0112 0111 0221 0332 0111 012 0225 0332 0114 0332	Building exterior Throughout Building Exterior Building Exterior Building Exterior Roof Throughout Throughout Throughout	1312424 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace 1312457 Kitchen Cabinetry, Stock Hardwood, Replace 1312455 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint 1312511 Window, Wood 24 SF, 1-2 Stories, Replace 1312505 Exterior Door, Wood Solid-Core, Replace 1312275 Roof, Asphalt Shingle 30-Year, Replace	20 10 30 25	10 5 16	10 5	22	-	\$229.									
er Elementary School / Building F E2012 er Elementary School / Building G B2011 er Elementary School / Building G B2021 er Elementary School / Building G B2032 er Elementary School / Building G B3011 er Elementary School / Building G C3012 er Elementary School / Building G C3025 er Elementary School / Building G C3025 er Elementary School / Building G D2014 er Elementary School / Building G D3032 er Elementary School / Building G D5012 er Elementary School / Building G D5012 er Elementary School / Building G D5012 er Elementary School / Building G D5022	0112 0111 0321 0332 0111 0112 0325 0332	Throughout Building Exterior Building Exterior Building Exterior Roof Throughout Throughout Throughout	1312457 Kitchen Cabinetry, Stock Hardwood, Replace 1312455 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint 1312511 Window, Wood 24 SF, 1-2 Stories, Replace 1312505 Exterior Door, Wood Solid-Core, Replace 1312275 Roof, Asphalt Shingle 30-Year, Replace	20 10 30 25	5 16	10 5	22	-	4==0.	.11 \$458				\$458				
or Elementary School / Building G B2011 or Elementary School / Building G B2021 or Elementary School / Building G B2032 or Elementary School / Building G B3011 or Elementary School / Building G B3011 or Elementary School / Building G C3025 or Elementary School / Building G C3032 or Elementary School / Building G D2014 or Elementary School / Building G D3032 or Elementary School / Building G D5012 or Elementary School / Building G D5012	011 021 032 011 012 025 032 014	Building Exterior Building Exterior Building Exterior Roof Throughout Throughout Throughout	1312455 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint 1312511 Window, Wood 24 SF, 1-2 Stories, Replace 1312505 Exterior Door, Wood Solid-Core, Replace 1312275 Roof, Asphalt Shingle 30-Year, Replace	10 30 25	5 16	5			\$327	.30 \$7,201				\$7,201				
Elementary School / Building G B2021 Elementary School / Building G B2032 Elementary School / Building G B3031 Elementary School / Building G C3012 Elementary School / Building G C3025 Elementary School / Building G C3032 Elementary School / Building G D2014 Elementary School / Building G D3032 Elementary School / Building G D3032 Elementary School / Building G D3032 Elementary School / Building G D5012 Elementary School / Building G D5012 Elementary School / Building G D5012	021 032 011 012 025 032 014	Building Exterior Building Exterior Roof Throughout Throughout Throughout	1312511 Window, Wood 24 SF, 1-2 Stories, Replace 1312505 Exterior Door, Wood Solid-Core, Replace 1312275 Roof, Asphalt Shingle 30-Year, Replace	30 25	16			SF	-			\$14,729		\$7,201		\$14,72		
r Elementary School / Building G B2032 r Elementary School / Building G B3011 r Elementary School / Building G C3012 r Elementary School / Building G C3025 r Elementary School / Building G C3032 r Elementary School / Building G D2014 r Elementary School / Building G D3032 r Elementary School / Building G D3032 r Elementary School / Building G D3032 r Elementary School / Building G D5012 r Elementary School / Building G D5012 r Elementary School / Building G D5012 r Elementary School / Building G D5022	032 011 012 025 032 014	Building Exterior Roof Throughout Throughout Throughout	1312505 Exterior Door, Wood Solid-Core, Replace 1312275 Roof, Asphalt Shingle 30-Year, Replace	25	16		4500		-	27 \$14,729		\$14,729					9	
ar Elementary School / Building G B3011 ar Elementary School / Building G C3012 ar Elementary School / Building G C3025 ar Elementary School / Building G C3032 ar Elementary School / Building G D2014 ar Elementary School / Building G D3032 ar Elementary School / Building G D3032 ar Elementary School / Building G D3032 ar Elementary School / Building G D5012 ar Elementary School / Building G D5012 ar Elementary School / Building G D5022	011 012 025 032 014	Roof Throughout Throughout Throughout	1312275 Roof, Asphalt Shingle 30-Year, Replace		13	14	12	EA		.20 \$15,710						\$15,710		
or Elementary School / Building G C3012 or Elementary School / Building G C3025 or Elementary School / Building G C3032 or Elementary School / Building G D2014 or Elementary School / Building G D3032 or Elementary School / Building G D3032 or Elementary School / Building G D3032 or Elementary School / Building G D5012 or Elementary School / Building G D5012 or Elementary School / Building G D5022	012 025 032 014	Throughout Throughout Throughout				12	6	EA	\$763.	.70 \$4,582					\$4,582			
or Elementary School / Building G C3025 or Elementary School / Building G C3032 or Elementary School / Building G D2014 or Elementary School / Building G D3032 or Elementary School / Building G D3032 or Elementary School / Building G D3032 or Elementary School / Building G D5012 or Elementary School / Building G D5012 or Elementary School / Building G D5022	025 032 014 032	Throughout Throughout	1312391 Interior Wall Finish, any surface, Pren & Paint	30	14	16	4800	SF	\$6.	.00 \$28,802							\$28,802	
or Elementary School / Building G C3032 or Elementary School / Building G D2014 or Elementary School / Building G D3032 or Elementary School / Building G D3032 or Elementary School / Building G D3032 or Elementary School / Building G D5012 or Elementary School / Building G D5022	032 014 032	Throughout	1312391 Interior Wall Finish, any surface, Prep & Paint	10	4	6	4500	SF	\$1.	.64 \$7,364		\$7,3	64				\$7,364	
or Elementary School / Building G D2014 or Elementary School / Building G D3032 or Elementary School / Building G D3032 or Elementary School / Building G D3032 or Elementary School / Building G D5012 or Elementary School / Building G D5022	014		1312363 Interior Floor Finish, Carpet Commercial Standard, Replace	10	4	6	3100	SF	\$8.	.18 \$25,366		\$25,3	66				\$25,366	
r Elementary School / Building G D3032 r Elementary School / Building G D3032 r Elementary School / Building G D3032 r Elementary School / Building G D5012 r Elementary School / Building G D5022	032		1312445 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	13	12	3100	SF	\$3.	.82 \$11,837					\$11,837			
r Elementary School / Building G D3032 r Elementary School / Building G D3032 r Elementary School / Building G D5012 r Elementary School / Building G D5022		Throughout	1312380 Sink/Lavatory, Vanity Top, Stainless Steel, Replace	30	14	16	3	EA	\$1,309.	.20 \$3,928							\$3,928	
r Elementary School / Building G D3032 r Elementary School / Building G D3032 r Elementary School / Building G D5012 r Elementary School / Building G D5022	032	Roof	1312390 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	1	14	1	EA	\$5,673.	.20 \$5,673						\$5,673		
er Elementary School / Building G D3032 er Elementary School / Building G D5012 er Elementary School / Building G D5022			1312461 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	1	14	1	EA	\$5,673.	.20 \$5.673						\$5,673		
er Elementary School / Building G D5012 er Elementary School / Building G D5022	132		1312519 Condensing Unit/Heat Pump, Split System, 4 Ton, Replace	15	1	14	1	EA	\$5,673.							\$5,673		
r Elementary School / Building G D5022					17		1	-		.70 \$7,310					67.240			
		·	1312560 Secondary Transformer, Dry, 30 kVA, Replace	30		13		EA						0040	\$7,310	0		
r Elementary School / Building G E2012			1312473 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace		10	10	4	EA	\$229.				1	\$916				
			1312421 Kitchen Cabinetry, Stock Hardwood, Replace	20	12	8	34	LF	_	.30 \$11,128			\$11,128					
r Elementary School / Portables B1015		-	1312510 Exterior Stair/Ramp Rails, Metal, Refinish	10	5	5	560	LF	-	.63 \$915		\$915				\$91		
r Elementary School / Portables B2011	011	Building Exterior	1312282 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	5	5	23000	SF	\$3.	.27 \$75,279		\$75,279				\$75,27	9	
er Elementary School / Portables B2011	011	Building Exterior- new restroom	1312329 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	3	7	1300	SF	\$3.	.27 \$4,255			\$4,255				\$4,255	
r Elementary School / Portables B2021	021	Building Exterior	1312309 Window, Aluminum Double-Glazed 24 SF, 1-2 Stories, Replace	30	19	11	38	EA	\$1,036.	.45 \$39,385				\$39,385	5			
Elementary School / Portables B3011	011	Roof- restroom	1312506 Roof, Modified Bituminous, Replace	20	10	10	900	SF	\$10.	.91 \$9,819				\$9,819				
Elementary School / Portables C1031	031	Common area restrooms	1312388 Toilet Partitions, Metal, Replace	20	10	10	10	EA	\$927.	.35 \$9,274				\$9,274				
r Elementary School / Portables C2011	011	Main entrance ramps	1312492 Interior Stair/Ramp Rails, Wood, Repair	0	0	0	300	LF	\$16.	.37 \$4,910 \$4,910								
Elementary School / Portables C3012			1312562 Interior Wall Finish, Fabric, Replace	15	7	8	22000			.18 \$48,004			\$48,004					
Elementary School / Portables C3012			1312544 Interior Wall Finish, Ceramic Tile, Replace	40	22	18	460	SF	_	.64 \$9,033			ψ10,001				\$9,033	
			<u> </u>		- 22	10							04.440				\$9,033	
Elementary School / Portables C3024			1312462 Interior Floor Finish, Vinyl Tile (VCT), Replace	15		8	760	SF	-	.46 \$4,146			\$4,146					
Elementary School / Portables C3024		Restroom-46	1312284 Interior Floor Finish, Vinyl Sheeting, Replace	15	7	8	180	SF	-	.64 \$1,375			\$1,375					
Elementary School / Portables C3024	024	Common area restrooms	1312362 Interior Floor Finish, Ceramic Tile, Replace	40	22	18	300	SF	\$19.	.64 \$5,891							\$5,891	
Elementary School / Portables C3025	025	Throughout	1312381 Interior Floor Finish, Carpet Commercial Standard, Replace	10	5	5	18000	SF	\$8.	.18 \$147,285		\$147,285				\$147,28	5	
r Elementary School / Portables C3032	032	Throughout	1312351 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	12	13	18000	SF	\$3.	.82 \$68,733					\$68,733	3		
Elementary School / Portables D2011	011	Restroom-46	1312349 Toilet, Tankless (Water Closet), Replace	30	14	16	2	EA	\$1,013.	.54 \$2,027							\$2,027	
Elementary School / Portables D2012	012	Common area restrooms	1312479 Urinal, Standard, Replace	30	12	18	3	EA	\$1,200.	.10 \$3,600							\$3,600	
Elementary School / Portables D2014	014	Restroom-46	1312460 Sink/Lavatory, Wall-Hung, Vitreous China, Replace	30	14	16	1	EA	\$1,636.	.50 \$1,637							\$1,637	
Elementary School / Portables D2018	018	Building exterior	1312293 Drinking Fountain, Outside/Site Style, Replace	15	6	9	2	EA	\$3,927.	.60 \$7,855			\$7,85	5				
r Elementary School / Portables D3052			1312397 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	17	3	1	EA	_	.50 \$6,001	\$6,001							
r Elementary School / Portables D3052			1312508 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	17	3	1	EA		.50 \$6,001	\$6,001							
		-						_										
Elementary School / Portables D3052			1312399 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	17	3	1	EA		.50 \$6,001	\$6,001							
Elementary School / Portables D3052			1312568 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	17	3	1	EA		.50 \$6,001	\$6,001							
Elementary School / Portables D3052	052	Rear of building-25	1312292 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA	\$6,000.	.50 \$6,001				\$6,001				
Elementary School / Portables D3052	052	Rear of building-23	1312425 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA	\$6,000.	.50 \$6,001				\$6,001				
Elementary School / Portables D3052	052	Rear of building-36	1312330 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA	\$6,000.	.50 \$6,001				\$6,001				
Elementary School / Portables D3052	052	Rear of building-33	1312355 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA	\$6,000.	.50 \$6,001				\$6,001				
Elementary School / Portables D3052	052	Rear of building-24	1312314 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA	\$6,000.	.50 \$6,001				\$6,001				
Elementary School / Portables D3052	052	Rear of building-37	1312377 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA	\$6,000.	.50 \$6,001				\$6,001				
Elementary School / Portables D3052		-	1312448 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA	\$6,000.	.50 \$6,001				\$6,001				
Elementary School / Portables D3052			1312438 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA		.50 \$6,001				\$6,001				
Elementary School / Portables D3052		-	1312318 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA		.50 \$6,001				\$6,001				
								_										
Elementary School / Portables D3052			1312542 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA		.50 \$6,001				\$6,001				
Elementary School / Portables D3052		-	1312392 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA		.50 \$6,001				\$6,001				
lementary School / Portables D3052		-	1312331 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA		.50 \$6,001				\$6,001				
Elementary School / Portables D3052	052	Rear of building-38	1312444 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA	\$6,000.	.50 \$6,001				\$6,001				
lementary School / Portables D3052	052	Rear of building-50	1312509 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA	\$6,000.	.50 \$6,001				\$6,001				
Elementary School / Portables D3052	052	Rear of building-34	1312334 Heat Pump, Wall-Mounted, 3.5 Ton, Replace	20	10	10	1	EA	\$6,000.	.50 \$6,001				\$6,001				
lementary School / Portables D5022	022	Building exterior- New restroom	1312447 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	20	3	17	3	EA	\$229.	.11 \$687							\$687	
Elementary School / Site B1015			1312466 Exterior Stair/Ramp Rails, Metal, Refinish	10	4	6	280	LF		.63 \$457		\$4	57				\$457	
Elementary School / Site B3011			1312573 Roof, Asphalt Shingle 30-Year, Replace	30	16	14	2200			.00 \$13,201		,				\$13,201		
Elementary School / Site B3011			1312408 Roof, Metal, Replace	40	20		2100	_		.18 \$29,784						Ţ.5,=V!		\$29,784
									_			#0.000						
Elementary School / Site D2018			1312471 Drinking Fountain, Outside/Site Style, Replace	15	10	5	1		_	60 \$3,928		\$3,928						\$3,928
Elementary School / Site D2021			1312443 Backflow Preventer, Domestic, 3", Replace	30	16	14	1			.20 \$5,673						\$5,673		
Elementary School / Site D2021	021	Site	1312299 Backflow Preventer, Domestic, 3", Replace	30	16	14	1	EA	\$5,673.	.20 \$5,673						\$5,673		

Location Name	Uniformat Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quan	antityUnit	.it U	Unit Cost * S	* Subtotal 2019	19 2020	2021	1 2022	2023 20	024 202	25 2026	2027	2028 202	29 2030 203	1 203	2033	Dra	M 20150[20]	Discussion Pur	MOSES O
Juniper Elementary School / Site	D2021	Site	131256°	Backflow Preventer, Domestic, 3", Replace	30	14	16	1	ı F	EA \$	\$5,673.20	\$5,673													\$5,673		\$5,673
Juniper Elementary School / Site	D4011	Site	131254°	Backflow Preventer, Fire Suppression, 10", Replace	30	18	12	1	ı F	EA \$19	\$19,638.00	\$19,638									\$19,638	8					\$19,638
Juniper Elementary School / Site	D5012	Site	131251°	13 Secondary Transformer, Dry, 30 kVA, Replace	30	29	1	1	ı F	EA \$	\$7,309.70	0 \$7,310	\$7,310														\$7,310
Juniper Elementary School / Site	D5012	Site	131256	Secondary Transformer, Dry, 30 kVA, Replace	30	29	1	1	, F	EA \$	\$7,309.70	0 \$7,310	\$7,310														\$7,310
Juniper Elementary School / Site	D5012	Site	131233°	33 Secondary Transformer, Dry, 30 kVA, Replace	30	18	12	1	ı F	EA \$	\$7,309.70	0 \$7,310									\$7,310	0					\$7,310
Juniper Elementary School / Site	G2022	Parking lot	131232	Parking Lots, Asphalt Pavement, Cut & Patch	0	0	0	2500	٠٥٥ ع	SF	\$6.00	00 \$15,001 \$15,001	1														\$15,001
Juniper Elementary School / Site	G2022	Parking lot	131232 ^f	Parking Lots, Asphalt Pavement, Seal & Stripe	5	2	3	59000	J00 E	SF	\$0.49	9 \$28,966			\$28,966				\$28,966			\$28,966	6			\$28,966	\$115,864
Juniper Elementary School / Site	G2022	Parking lot	131252 ^r	Parking Lots, Asphalt Pavement, Mill & Overlay	25	17	8	59000	J00 E	SF	\$3.82	2 \$225,292						\$	225,292								\$225,292
Juniper Elementary School / Site	G2031	Sidewalk	131245′	Pedestrian Pavement, Sidewalk, Concrete Sections/Small Areas, Repair	ir 50	48	2	240	40 ع	SF	\$21.82	\$5,237		\$5,237	7												\$5,237
Juniper Elementary School / Site	G2047	Playground	131252/	Play Surfaces & Sports Courts, Asphalt, Seal & Stripe	5	2	3	34000	3 00C	SF	\$0.49	9 \$16,655			\$16,655				\$16,655			\$16,655	5			\$16,655	\$66,621
Juniper Elementary School / Site	G2047	Playground	131249°	93 Play Surfaces & Sports Courts, Asphalt, Mill & Overlay	25	17	8	34000	ع 200	SF	\$3.82	2 \$129,829						\$	129,829								\$129,829
Juniper Elementary School / Site	G2047	Playground	131253 ^r	36 Sports Apparatus, Basketball Backstop, Replace	25	14	11	2	2 F	EA \$10	\$10,364.50	\$20,729									\$20,729						\$20,729
Juniper Elementary School / Site	G2047	Playground	131246	Play Structure, Small, Replace	20	7	13	1	ı F	EA \$10	\$10,910.00	\$10,910										\$10,910	0				\$10,910
Juniper Elementary School / Site	G2047	Playground	131251′	18 Play Structure, Small, Replace	20	6	14	1	ı F	EA \$10	\$10,910.00	\$10,910											\$10,910				\$10,910
Juniper Elementary School / Site	G2047	Playground	131235°	Play Surfaces & Sports Courts, Wood Chips, 3" Depth, Replace	20	5	15	1800	ع 00ر	SF	\$0.98	98 \$1,758												\$1,758			\$1,758
Juniper Elementary School / Site	G2047	Playground	131242	Play Surfaces & Sports Courts, Poured-in-place Rubber, Replace	20	0	20	3500	ع 00ر	SF	\$22.91	1 \$80,189														\$80,189	\$80,189
Juniper Elementary School / Site	G2047	Playground	131227	74 Play Structure, Small, Replace	20	0	20	1	ı F	EA \$10	\$10,910.00	\$10,910														\$10,910	\$10,910
Juniper Elementary School / Site	G2049	Site	131227′	76 Shed, Wooden Framed, Asphalt Shingles, Replace	30	12	2 18	80	ع 0ر	SF	\$43.64	\$4 \$3,491														\$3,491	\$3,491
Juniper Elementary School / Site	G2057	Site	131226′	69 Irrigation System, , Replace/Install	25	12	2 13	1550	۶ 000ر	SF	\$3.82	2 \$591,868										\$591,868	8				\$591,868
Juniper Elementary School / Site	Z105X	Main entrance	131427′	ADA, Miscellaneous, Signage, Directional, Wall-Mounted, Install	0	0	0	4	4 F	EA	\$240.13	3 \$961 \$961	1														\$961
Totals, Unescalated												\$28,508	8 \$103,263	\$308,779	\$584,781	\$0 \$694,6	\$97,66	5 \$40,278 \$	606,875	\$7,855 \$712,27	79 \$125,792 \$182,91	2 \$800,73	5 \$477,754	\$789,433	\$168,466 \$4,942	2 \$1,569,004 \$16,365 \$139,801	\$7,460,160
Totals, Escalated (3.0% inflation, comp	pounded annu	aallv)										\$28,50	8 \$106,361	\$327,584	4 \$639,006	\$0 \$805,3	\$14 \$116,618	8 \$49,537 \$	768,771	\$10,249 \$957,24	43 \$174,126 \$260,78	8 \$1,175,906	6 \$722,646	\$1,229,910	\$270,338 \$8,169	9 \$2,671,125 \$28,696 \$252,496	\$10,603,393

Appendix G: Equipment Inventory List

10 CONVEYING											
dex ID	UFCode	Component	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1312339	D1013	Wheelchair Lift	750 LBS	Juniper Elementary School / Building B	Stage	Inaccessible					
20 PLUMBING											
dex ID	UFCode	Component	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1312428	D2021	Backflow Preventer		Juniper Elementary School / Site	Site	Inaccessible	Inaccessible	Inaccessible			
1312569	D2021	Backflow Preventer		Juniper Elementary School / Site	Site	Inaccessible	Inaccessible	Inaccessible			
1312443	D2021	Backflow Preventer		Juniper Elementary School / Site	Site	Inaccessible	Inaccessible	Inaccessible			
1312299	D2021	Backflow Preventer		Juniper Elementary School / Site	Site	Inaccessible	Inaccessible	Inaccessible			
1312564	D2023	Domestic Circulation/Booster Pump	7.5 HP	Juniper Elementary School / Site	Site	Inaccessible	Inaccessible	Inaccessible	2019		
1312441	D2023	Water Heater	15 Gallon	Juniper Elementary School / Building 41-44	Custodian closet	Inaccessible	Inaccessible	Inaccessible			
1312348	D2023	Water Heater	30 Gallon	Juniper Elementary School / Building C	Janitor room	A. O. Smith	ENT30100	1620J008084			
1312310	D2023	Water Heater	50 Gallon	Juniper Elementary School / Building A	Custodian room	American Standard	Inaccessible	Inaccessible			
1312534	D2023	Water Heater	75 Gallon	Juniper Elementary School / Building B	Janitor room	A. O. Smith	FCG 75 300	9200472000	2015		
	D2042	Roof Drain		Juniper Elementary School	Throughout						
0 HVAC											
x ID	UFCode	Component	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Q
1312453	D3032	Condensing Unit/Heat Pump	3 Ton	Juniper Elementary School / Building A	Roof	Carrier	25HHA436A300	4915X99651	2015		
1312322	D3032	Condensing Unit/Heat Pump	3 Ton	Juniper Elementary School / Building E	Roof	Carrier	25HHA436A300	2815X90761	2015		
1312294	D3032	Condensing Unit/Heat Pump		Juniper Elementary School / Building A	Roof	Carrier	25HNA436A300	1019X51032	2019		
1312546	D3032	Condensing Unit/Heat Pump	3.5 Ton	Juniper Elementary School / Building E	Building E	Carrier	25HCE442A300	2718E13018	2018		
1312490	D3032	Condensing Unit/Heat Pump	3.5 Ton	Juniper Elementary School / Building E	Roof	Carrier	25HHA430A300	3315X93143	2015		
1312570	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building D	Roof	Carrier	25HHA448A0050010	1419X19937	2019		
1312390	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building G	Roof	Carrier	25HHA448A500	2518X48494	2018		
1312514	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building D	Roof	Carrier	25HHA448A0050010	2018X35697	2018		
1312433	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building C	Roof Roof	Carrier	25HHA448A500	1419X20301	2019		
1312280 1312482	D3032 D3032	Condensing Unit/Heat Pump Condensing Unit/Heat Pump	4 Ton 4 Ton	Juniper Elementary School / Building E	Roof	Carrier Carrier	25HHA448A500 25HHA448A500	0916X87070 0919X43195	2016		
1312354	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building C Juniper Elementary School / Building C	Roof	Carrier	25HHA448A500	2018X35735	2019		
1312354	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building C Juniper Elementary School / Building C	Roof	Carrier	25HHA448A500	3818X29731	2018		
1312461	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building G	Roof	Carrier	25HHA448A500	3818X29784	2018		
1312519	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building G	Roof	Carrier	25HHA448A500	3818x29775	2018		
1312342	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building C	Roof	Carrier	25HHA448A500	3418X84669	2018		
1312373	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building E	Roof	Carrier	25HHA448A0050010	0316X99154	2016		
1312484	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building D	Roof	Carrier	25HHA448A0050010	1419X20245	2019		
1312372	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building D	Roof	Carrier	25HHA448A0050010	0919X43220	2019		
1312379	D3032	Condensing Unit/Heat Pump	4 Ton	Juniper Elementary School / Building D	Roof	Carrier	25HHA448A0050010	3818X29745	2018		
1312296	D3032	Condensing Unit/Heat Pump	5 Ton	Juniper Elementary School / Building F	Roof	Carrier	25HHA460A500	3518X47021	2018		
1312288	D3032	Condensing Unit/Heat Pump	5 Ton	Juniper Elementary School / Building F	Roof	Carrier	25HHA460A500	4618X32729	2018		
1312403	D3032	Condensing Unit/Heat Pump	5 Ton	Juniper Elementary School / Building A	Roof		YHJD60S44S5B	W1K4107350			
1312394	D3032	Condensing Unit/Heat Pump4 Ton	4 Ton	Juniper Elementary School / Building D	Roof	Carrier	25HHA448A0050010	1419X20183	2019		
1312384	D3032	Ductless Split System	2 Ton	Juniper Elementary School / Building A	Roof	Fujitsu	AOU24RLXFW	KTN026876			
1312516	D3041	Air Handler (AHU)	1000 CFM	Juniper Elementary School / Building E	Attic	Carrier	FB4CNP030	2016A74857	2016		
1312417	D3041	Air Handler (AHU)	1200 CFM	Juniper Elementary School / Building E	Attic	Carrier	FB4CNP036	2416A73781	2016		
1312365	D3041	Air Handler (AHU)	400 CFM	Juniper Elementary School / Building A	Attic	Advanced Distributor Products	AM600CT	7114C19506	2014		
1312316	D3041	Air Handler (AHU)	400 CFM	Juniper Elementary School / Building A	Attic	Advanced Distributor Products	FB40AP036	1519F20124	2019		
1324927	D3041	Air Handler (AHU)	400 CFM	Juniper Elementary School / Building A	Attic	Advanced Distributor Products	AM600CT		2014		
1312344	D3041	Air Handler (AHU)	1600 CFM	Juniper Elementary School / Building D	Attic	Carrier	FB4CNP048	1519F05267	2019		
1312571	D3041	Air Handler (AHU)	1600 CMF	Juniper Elementary School / Building D	Attic	Carrier	FB4CNP048	2319F26459	2019		
1312558	D3041	Air Handler (AHU)	1600 CFM	Juniper Elementary School / Building G	Above ceiling	Carrier	FBCN2048	0440500000	2019		
1312440 1312483	D3041 D3041	Air Handler (AHU) Air Handler (AHU)	1600 CFM 1600 CFM	Juniper Elementary School / Building D	Attic Above ceiling	Carrier Carrier	FB4CNP048 FBCN2048	2119F20296 0919F05998	2019		
1312463	D3041			Juniper Elementary School / Building G		Carrier	FB4CNP048		2019		
1312297	D3041	Air Handler (AHU) Air Handler (AHU)	1600 CFM 1600 CFM	Juniper Elementary School / Building E Juniper Elementary School / Building C	Attic Attic	Carrier	FB4CNP048	1816A91001 1519F05268	2019		
1312209	D3041	Air Handler (AHU)	1600 CFM	Juniper Elementary School / Building C Juniper Elementary School / Building C	Attic	Carrier	FB4CNP048	Inaccessible	2019		
1312494	D3041	Air Handler (AHU)	1600 CFM	Juniper Elementary School / Building D	Attic	Carrier	FB4CNP048	1519F05261	2019		
1312336	D3041	Air Handler (AHU)	1,600 CFM	Juniper Elementary School / Building C	Attic	Carrier	FB4CNP048	1519F05265	2019		
1312369	D3041	Air Handler (AHU)	1600 CFM	Juniper Elementary School / Building D	Attic	Carrier	FB4CNP048	2119F20297	2019		
1312364	D3041	Air Handler (AHU)	1600 CFM	Juniper Elementary School / Building D	Attic	Carrier	FB4CNP048	2319F26456	2019		
1312498	D3041	Air Handler (AHU)	1600 CFM	Juniper Elementary School / Building C	Attic	Carrier	FB4CNP048	1519F05256	2019		
1312528	D3041	Air Handler (AHU)	1600 CFM	Juniper Elementary School / Building G	Above ceiling	Carrier	FBCN2048	1519F05255	2019		
1312358	D3041	Air Handler (AHU)	1600 CFM	Juniper Elementary School / Building C	Attic	Carrier	FB4CNP048	2310F26453	2019		
1312487	D3041	Air Handler (AHU)	1600 CFM	Juniper Elementary School / Building E	Attic	Carrier	FB4CNP048	2416A87345	2016		
1312530	D3041	Air Handler (AHU)	2000 CFM	Juniper Elementary School / Building F	Utility closet	Carrier	FB4CNP061	511BF12362	2018		
1312432	D3041	Air Handler (AHU)	2000 CFM	Juniper Elementary School / Building F	Utility closet	Carrier	FB4CNP061	511BF12389	2018		
1312278	D3042	Exhaust Fan	No tag/plate found	Juniper Elementary School / Building 41-44	Roof	Illegible	Illegible	Illegible			
1312347	D3042	Exhaust Fan	No tag/plate found	Juniper Elementary School / Building 41-44	Roof	Illegible	Illegible	Illegible			
1312397	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-46	Bard	WH421-A05VX4XXX	153P062287354-02			
1312292	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-25	Bard	WH421-A05VX4XXX	126H041929369-02			
1312425	D3052	Heat Pump	3.5 ton	Juniper Elementary School / Portables	Rear of building-23	Bard	WH421-A05VX4XXX	126D041902203-02			
	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-07	Bard	AVP42HPA10NB-1000BI	EM73933			
1312508						Bard	WH421-A10VX4XXX	126F971106807-02			
1312330	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-36	Baro		1201 37 1100007-02			
	D3052 D3052 D3052	Heat Pump Heat Pump Heat Pump	3.5 Ton 3.5 Ton	Juniper Elementary School / Portables Juniper Elementary School / Portables	Rear of building-33	Illegible Bard	PNY032KCRXA08 WH421-A05VX4XXX	Inaccessible 126F052042219-02			

58	1312377	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-37	Bard	WH421-A10VX4XXX	136M97 (1) (399 (1) - [or Discussion	வ பொருவை	eae Amli
59	1312448	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-52	Bard	WH421-A10Vx4XXX	126M971162142-01		in an bos	inni san
60	1312399	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-03	Illegible	Illegible	Illegible			
61	1312438	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-27	Bard	WH421-A05VX4XXX	126F052042216-02			
62	1312318	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-26	Bard	WH421-A05VX4XXX	126H041929368-02			
63	1312568	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-45	Bard	No tag/plate found	No tag/plate found			
64	1312542	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-22	Bard	WH421-A05VX4XXX	126H041929365-02			
65	1312392	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-28	Bard	WH421-A05VP4XXX	126F052042220-02			
66	1312331	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-51	Bard	WH421-A10Vx4XXX	126M971162145-01			
67	1312444	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-38	Bard	WH421-A10Vx4XXX	126F971106017-02			
68	1312509	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-50	Bard	WH421-A10Vx4XXX	126M971162142-01			
69	1312334	D3052	Heat Pump	3.5 Ton	Juniper Elementary School / Portables	Rear of building-34	Illegible	Illegible	Illegible			
70	1312522	D3052	Packaged Unit (RTU)	20 Ton	Juniper Elementary School / Building B	Ground level	Carrier	48LJD024	4092F20210	1992		
71	1312370	D3052	Packaged Unit (RTU)	3 Ton	Juniper Elementary School / Building 41-44	Roof	Carrier	50VT-C3630TP	1117C37287	2017		
72	1312423	D3052	Packaged Unit (RTU)	3 Ton	Juniper Elementary School / Building 41-44	Roof	Carrier	Illegible	Illegible	2011		
73	1312340	D3052	Packaged Unit (RTU)	3 Ton	Juniper Elementary School / Building 41-44	Roof	Carrier	Illegible	Illegible			
74	1312382	D3052	Packaged Unit (RTU)	3 Ton	Juniper Elementary School / Building 41-44	Roof	Carrier	Illegible	Illegible			
75	1312411	D3052	Packaged Unit (RTU)	4 Ton	Juniper Elementary School / Building B	Roof	Carrier	50SS-04830	2294G40559	1994		
76	1312325	D3052	Packaged Unit (RTU)	7.5 Ton	Juniper Elementary School / Building B	Roof	Carrier	50HJQ008621HY	1002G50575	2002		
77	1312521	D3052	Packaged Unit (RTU)	7.5 Ton	Juniper Elementary School / Building E	Roof	Carrier	38AUQA08A0A6A0	0418C94856	2018		
			Tackaged offic (KTO)	7.5 1011	dumper Elementary defident building E	1001	Gamer	30/10/4/0/10/10/10/10/10/10/10/10/10/10/10/10/1	0+1003+000	2010		
D40 FI	RE PROTECTI	ON										
Index	ID	UFCode	Component	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	1312549	D4011	Backflow Preventer		Juniper Elementary School / Site	Site	No tag/plate found	No tag/plate found	No tag/plate found			
D50 EL	ECTRICAL.											
Index	ID	UFCode	Component	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	1312551	D5012	Building/Main Switchboard	· ,	Juniper Elementary School / Site	Site	Pacific electric			2005		
2	1312458	D5012	Building/Main Switchboard	600 AMP	Juniper Elementary School / Building A	Electrical room	Cutler-Hammer					
3	1312279	D5012	Distribution Panel	225 AMP	Juniper Elementary School / Building 41-44	Building interior				1987		
4	1312538	D5012	Distribution Panel	225 AMP	Juniper Elementary School / Building A	Building interior	Siemens			2002		
5	1312454	D5012	Distribution Panel	250 AMP	Juniper Elementary School / Building B	Electrical room	Siemens			2002		
6	1312298	D5012	Distribution Panel	400 AMP	Juniper Elementary School / Building C	Building exterior	Inaccessible	Inaccessible	Inaccessible			
7	1312281	D5012	Main Distribution Panel	225 AMP	Juniper Elementary School / Building D	Building interior						
8	1312450	D5012	Secondary Transformer	10 KVA	Juniper Elementary School / Building A	Electrical room	Zinsco					
9	1312513	D5012	Secondary Transformer	30 KVA	Juniper Elementary School / Site	Site	Illegible	Illegible	Illegible			
10	1312557	D5012	Secondary Transformer	37.5 KVA	Juniper Elementary School / Building C	Electrical room	Square D	illogisto	illogiblo			
11	1312561	D5012	Secondary Transformer	30 KVA	Juniper Elementary School / Site	Site	No tag/plate found	No tag/plate found	No tag/plate found			
12	1312368	D5012	Secondary Transformer	30 KVA	Juniper Elementary School / Building F	Utility closet	Federal Pacific	Tto agriculto found	Tto tag/plato lound			
13	1312560	D5012	Secondary Transformer	33 111/1	Juniper Elementary School / Building G	Utility closet	Federal Pacific			2002		
14	1312333	D5012	Secondary Transformer	30 KVA	Juniper Elementary School / Site	Site	No tag/plate found	No tag/plate found	No tag/plate found	2002		
15	1312304	D5012	Switchboard	500 AMP	Juniper Elementary School / Building C	Electrical room	Westinghouse	No tag/plate found	140 tag/plate lound			
16	1312473	D5022	Light Fixture	300711411	Juniper Elementary School / Building G	Building exterior	vvestingriouse					4
17	1312473	D5022	Light Fixture		Juniper Elementary School / Portables	Building exterior- New restroom				2016		3
18	1312447	D5022	Light Fixture		Juniper Elementary School / Portables Juniper Elementary School / Building E	Building exterior Building exterior				2010		4
19	1312434	D5022	Light Fixture		Juniper Elementary School / Building A	Building exterior						
20	1312434	D5022	Light Fixture		Juniper Elementary School / Building C	Building exterior						
21	1312515	D5022	Light Fixture			Building exterior						3
22	1312565	D5022	Light Fixture Light Fixture		Juniper Elementary School / Building B	Building exterior						2
23					Juniper Elementary School / Building 41-44							4
24	1312478 1312424	D5022 D5022	Light Fixture Light Fixture		Juniper Elementary School / Building D	Building exterior Building exterior						2
25	1312424	D5022 D5037	Fire Alarm Control Panel		Juniper Elementary School / Building F Juniper Elementary School / Building A	Data room	Siemens					
		D3037	File Alaim Control Faller		Jumper Elementary School / Building A	Data 100III	Siemens					
E10 E0	QUIPMENT											
Index	ID	UFCode	Component	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	1312300	E1028	Defibrillator (AED)		Juniper Elementary School / Building A	Front office						
2	1312540	E1093	Commercial Convection Oven, Double		Juniper Elementary School / Building B	Kitchen	Vulcan	Inaccessible	Inaccessible			
3	1312499	E1093	Commercial Exhaust Hood, 8 to 10 LF	8 LF	Juniper Elementary School / Building B	Kitchen						
4	1312539	E1093	Commercial Food Warmer		Juniper Elementary School / Building B	Kitchen	BevLes	No tag/plate found	No tag/plate found			
5	1312476	E1093	Commercial Food Warmer		Juniper Elementary School / Building B	Kitchen	вкі	No tag/plate found	No tag/plate found			
6	1312395	E1093	Commercial Freezer, 2-Door Reach-In		Juniper Elementary School / Building B	Kitchen	Traulsen	ALT232WUT-FHS	T02633H05			
7	1312378	E1093	Commercial Freezer, 2-Door Reach-In		Juniper Elementary School / Building B	Kitchen	Traulsen	ALT232WUT-FHS	T91351H08			
8	1312470	E1093	Commercial Refrigerator, 1-Door Reach-In		Juniper Elementary School / Building B	Kitchen	Utility	R-30-SS-1S-D	7226G			
9	1312307	E1093	Commercial Refrigerator, 1-Door Reach-In		Juniper Elementary School / Building B	Kitchen	Utility	RIR-30-SS-1S-H	6295C			
10	1312517	E1093	Commercial Refrigerator, 2-Door Reach-In		Juniper Elementary School / Building B	Kitchen	Traulsen	AHT232WUT-FHS	T02618H05			
	1212472	E1002	Commercial Refrigerator 2 Deer Reach In		Juniper Elementery School / Building B			A UT222W/LIT EUC	T22020H00			

Kitchen

Kitchen

Traulsen

Utility

Juniper Elementary School / Building B

Juniper Elementary School / Building B

1312472

1312332

E1093

E1093

Commercial Refrigerator, 2-Door Reach-In

Commercial Refrigerator, 2-Door Reach-In

T23939H09

7454

AHT232WUT-FHS

RIR-60-SS-2S-H