

Click to prove  
you're human





## Fluke networks linkrunner at 2000 firmware update

Search and Filter The Versiv Firmware v6.13 Build 2 supports various certification products, including DSX CableAnalyzer, CertiFiber Pro, and OptiFiber Pro. This firmware requires LinkWare 11.6 for installation. Support is available for Versiv firmware v6.5 build 5 or higher, as well as LinkIQ firmware v1.0 or higher. Internet access is necessary during the installation process. This operating system is designed for the CableIQ Tester, which can be loaded using the CableIQ Reporter Software. A zipfile is included to upgrade a FI-3000 FiberInspector probe to Firmware v2.2.1. Users can download this update and instructions to proceed with the upgrade. The latest software updates from Fluke are available, including product firmware, software upgrades, and standalone applications. Reddit's use of cookies and similar technologies improves user experience. By accepting all cookies, users agree to Reddit's use of these technologies for services and site improvement, personalized content, and advertising measurement. Users are currently offline and viewing a read-only version of the page. Updating Firmware (LinkRunner AT 1000/2000) To update this firmware, users must have a valid AllyCare support contract on their unit. It is recommended to ensure the unit is fully charged before proceeding. Updating Software via Link-Live The LinkRunner AT 1000/2000 cannot be updated through the Link-Live Cloud Service. However, users must be on version 2.4.3 or later and claim their unit to use this service. LinkRunner AT Manager Software Installation The LinkRunner AT Manager software is available for download via the Link-Live account. To download: 1. Log in to your Link-Live account. 2. Expand the Support option and select Software Downloads. 3. Click on the LinkRunner AT Manager button to download. 4. Install this application on your computer, connect the LinkRunner AT via the provided cable, and launch the LinkRunner AT manager software. Firmware Update Steps: 1. Launch the LinkRunner AT manager software and click TOOLS. 2. Select UPDATE Firmware and browse for the firmware file. 3. Follow on-screen directions; the update may take approximately 5 minutes. 4. The unit will reboot initially; keep it connected to your PC - do not remove the cable until instructed. 5. The unit will continue updating and then reboot again, at which point you will receive a notification to remove the USB cable.

[Fluke networks linkrunner at 2000 firmware.](#) [Linkrunner firmware update.](#) [Linkrunner 2000 firmware.](#) [Fluke linkrunner at 2000 firmware.](#)