MATERIAL SAFETY DATA SHEET

Effective Date: August 30, 2018

I. IDENTIFICATION

a. Product Name: Cardinal Acoustics Panels
b. Technical Name: Wood Wool Acoustic Panel

II. HAZARD IDENTIFICATION

a. Classification of Substance or Mixture:
   i. The product is not classified according to OSHA Hazard Communications Standard (29 CFR 1910.1200).

b. Information Concerning Particular Hazard for Human Environment:
   i. The product is not to be labeled due to the calculation procedure of OSHA Hazard Communications Standard (29 CFR 1910.1200). c. Classification System:

c. Classification System:
   i. The classification is according to the latest edition of OSHA Hazard Communication Standard (29 CFR 1910.1200).

III. COMPOSITION/INFORMATION ON INGREDIENTS

a. Poplar Wood Wool Fiber: 55.00%
b. Water: 22.00%
c. Magnesium Oxide: 10.00%
d. Silicon Dioxide: 6.00%
e. Magnesium Sulphate: 5.50%
f. Aluminum Oxide: 1.50%

IV. FIRST-AID MEASURES

a. General description: No special measures required
b. After Inhalation: Supply fresh air; consult doctor in case of complaints
c. After skin contact: Generally, the product does not irritate the skin
d. After eye contact: Rinse opened eye for several minutes under running water
e. After swallowing: If symptoms persist, call doctor

V. FIRE-FIGHTING MEASURES

a. Suitable extinguishing agents:
   i. Use fire-fighting measures that suit the environment
b. Special hazards arising from the substance or mixture:
   i. No further relevant information available

CARDINAL ACOUSTICS
AN ACOUSTICAL WOOD FIBER COMPANY

For more information, visit cardinalacoustics.com or call us at 614.721.3001

Email: info@cardinalacoustics.com

CORPORATE OFFICES
2941 Donnylane Blvd.
Columbus, OH 43235

WAREHOUSE AND FABRICATION PLANT
721 Springfield Street
Dayton, Ohio 45403

MATERIAL SAFETY DATA SHEET, CONT.

VI. EMPLOYEE PROTECTION RECOMMENDATIONS

a. Eye Protection:

i. Eye goggles or safety glasses with shields recommended when handling, sawing, routing, etc.

b. Skin Protection:

i. Protect from mechanical abrasion. Long sleeve shirts and gloves recommende

c. Respiratory Protection:

i. Mechanically filtering dust masks recommended when handling, sawing, routing, etc.

VII. ADDITIONAL INFORMATION

a. Precautions to be taken in handling and storage:

i. Store panels with adequate aisle ways to permit access to all areas

ii. Provide adequate blocking to maintain straight and plumb stacks

iii. Avoid direct contact with open flames or torches

b. Disposal of wood wool panels

i. Do not allow dust or scrap to accumulate. Keep working areas clean and orderly.

ii. Scrap disposal should be done according to good industrial practice and environmental protection regulations. A sanitary landfill should be used when possible.

CARDINAL ACOUSTICS
AN ACOUSTICAL WOOD FIBER COMPANY

For more information, visit cardinalacoustics.com or call us at 614.721.3001

Email: info@cardinalacoustics.com

CORPORATE OFFICES
2941 Donnylane Blvd.
Columbus, OH 43235

WAREHOUSE AND FABRICATION PLANT
721 Springfield Street
Dayton, Ohio 45403