

PXI-501 ACS-001

Breakout box for easy access to PXI-501 functions

Overview

The PXI-501 ACS-001 is an extension for the PXI-501. It provides 4mm sockets do directly connect a DUT to the PXI-501 source and measurement functionality. It's especially recommended for laboratory environments and debugging purpose.



Features

- D-Sub 50 cable with 30cm length
- 4mm sockets for PMU force and sense signals
- Phoenix terminals for analog inputs and outputs

Global Deployment & Service

Europe

DE	info@konrad-technologies.de
UK	sales-uk@konrad-technologies.co.uk
Americas	info-usa@konrad-technologies.com

Asia & Pacific

CN	china.info@konrad-technologies.cn
IN	Info-india@konrad-technologies.com
KR	Info-korea@konrad-technologies.com

konrad
... technologies ...
www.konrad-technologies.com