

SITE SURVEY REQUIREMENTS - WALL PANELLING

Please read through the site survey requirements thoroughly and confirm by email when your site is ready for the final measurements to be taken

- The latest drawings including elevations have been sent to Saligo Design
- Walls have been prepared to a flat and smooth standard i.e. plastered and sealed or covered in PLY etc wherever our product will be fitted.
- 10mm minimum thickness support for wall panelling (skirting) or baton fitted to support.
- All BASE and WALL CABINETS installed and in final position.
- LIGHT PELMETS, CORNICES and UNDER -PELMET LIGHTS must be in place for site survey
- ALL BOXING AROUND PIPES FITTED
- ALL FITTINGS to go onto the glass must have been fitted in the final position and then removed with the hole positions clearly marked
- All ELECTRICAL BACK BOXES fitted in final position with face plates screwed on where possible (minimum 50mm from edge of the glass and 15mm between sockets)
- THE AREA HAS BEEN COMPLETELY CLEARED as the site surveyor cannot be responsible for breakage or damage if they move any items
- The customer or an authorised representative will be on site to allow access into the property and instruct the site surveyor on design specification (If an authorised representative is not on site, the survey will be ABORTED)

Please Note: Once the site survey has been completed, it will not be possible to add or alter fixtures, fittings or walls in any way

Parking for Site Survey & Installation

- Confirm parking options
- If free parking is not available, a parking permit will be arranged for the date of the site survey for the Site Surveyor
- If free parking is not available and a parking permit cannot be supplied for the date of the site survey, please note this could affect the Site Surveyor's punctuality

By confirming the area is ready for a Site Survey, you accept that a £200 fee plus VAT is payable for any survey or installation that is cancelled within 48 hours of the agreed time or if the site fails to meet the requirements detailed above. Incomplete surveys or installations will also incur additional direct costs, such as fuel, parking etc.