


IoT Installation guide

Step 1

Find the battery and main power supply wires: Positive & Negative



Step 2

Cut the main wire (+) positive



Step 3 - Connect

Connect IoT Red wire to the scooter + positive directly to the battery

Connect IoT Green wire to the scooter (+) positive controller side

Step 4

Expose at the negative cable 1cm of wire

Connect IoT black wire to the scooter — negative where it was expose

