

Report of Thorough Examination GA1

Ballybrit, Parkmore, Co. Galway. 091 – 394699 info@leeng.ie www.leeng.ie

Customer Information Date: 2022-07-18

Name: Maverick Contractors Ltd.		Address: IDA Business Park		
Plant ID: 2028		Tu	Tuam Road	
1 14111 121 2020		Co	o. Galway	
Equipment Information				
Name: OAT 000F0 OB		Coriol Num	lber: CAT0308ECFJX13588	
Name: CAT 308E2 CR				
Address: Adamstown	Equipment Type: Excavator			
Dublin	Year: 2019			
Co. Dublin	Sa	fe Working Load	Configuration	
	830k	Kgs.	As per manufacturers specifications	
Examination Information				
Date of Test: 2022-07-18		Next Tes	t Date: 2023-07-17	
Test Pur	pose:		Examination Purpose:	
Specific Test:		Examinatio	The state of the s	
Particulars of tests carried	d out:	Parts	s not available for examination:	
Full Visual Examination		All Parts Available		
Defect which is a danger to persons:		Repair, Renewal or Alteration required to remedy this defect:		
No apparent defects		None		
Defect which could		me for defect	Repair, Renewal or Alteration	
become a danger to persons:		ng a danger:	required to remedy this defect:	
Main Hoist Ram Leaking Beacon Not Working	0-1 Month 0-1 Week		Repair As Necessary Repair As Necessary	
This item is safe to use	: Yes	Signe	a: Niall Francis	

CITB UK, Lloyds British UK.