



Company: MAVERIC CONTRACTORS LTD

REPORT OF THOROUGH EXAMINATION

Reports of result of Thorough Examination of EXCAVATORS

CAT 308CR DIESEL HYDRAULIC TRACK EXCAVATOR ON RUBBER

Item Name: TRACKS BOOM 3.2 MTR DIPPER 2.3

MTR

CRSNR: HTMD2605 Serial Number: cat00308jgw802616

Proof Load: 28 ARD NA GAOIGTHE, UPPER CLYBAWN ROAD, GALWAY, ,

SWL: **830kgs** Previous Inspection:

Manufacturer: caterpillar Inspected Date: 25/05/2022

Year of Manufacture: Next Inspection Date: 25/05/2023

Notes:

| CERTIFICATION | | |
|---------------------------------|---------|--|
| THOROUGH EXAMINATION | Pass | |
| PURPOSE OF THOROUGH EXAMINATION | Testing | |
| DEFECTS FOUND | NONE | |

| | Checklist | Status |
|----|---|----------|
| 1 | Has a preventative maintenance been carried out on the asset? | NO |
| 2 | Has the asset been load tested? | YES |
| 3 | UNDERCARRIAGE - Crawler Pads | A - Pass |
| 4 | UNDERCARRIAGE - Link Pins | A - Pass |
| 5 | UNDERCARRIAGE - Adjustment of Tracks | A - Pass |
| 6 | UNDERCARRIAGE - Operation of Tracks | A - Pass |
| 7 | UNDERCARRIAGE - Hydraulic motors pipe work and hoses | A - Pass |
| 8 | UNDERCARRIAGE - Outrigger/Blade condition | A - Pass |
| 9 | UNDERCARRIAGE - Axle and tyres condition | D - N/A |
| 10 | TURNTABLE - Slew bearing, wear, bolting, general condition | A - Pass |
| 11 | TURNTABLE - Main turntable structure | A - Pass |
| 12 | TURNTABLE - Guarding and panels | A - Pass |
| 13 | TURNTABLE - Power unit and pumps | A - Pass |
| 14 | TURNTABLE - Valve banks, pipe work and hoses | A - Pass |
| 15 | TURNTABLE - Operator cabin general condition glass etc | A - Pass |
| 16 | TURNTABLE - Counterweight | A - Pass |
| 17 | BOOM - Boom root pin and brush wear | A - Pass |



Unit 11 Crag Crescent, D22 YY48, Ireland T +351 1 457 0021 hoistech.ie



The lifting specialists.

| 18 | BOOM - Boom general consition | A - Pass |
|----|--|----------|
| 19 | BOOM - Boom lift cylinder | A - Pass |
| 20 | BOOM - Boom check valves | A - Pass |
| 21 | BOOM - Boom hydraulic pipes and hoses | A - Pass |
| 22 | BOOM - Welding and steelwork for cracks and damages | A - Pass |
| 23 | BOOM - Upper pin and bush to dipper arm | A - Pass |
| 24 | BOOM - Pins and bushes on lift cylinders | A - Pass |
| 25 | DIPPER - Dipper pins and bushes | A - Pass |
| 26 | DIPPER - Linkage arms and bushes | A - Pass |
| 27 | DIPPER - Dipper cylinder | A - Pass |
| 28 | DIPPER - Hoses and pipe work | A - Pass |
| 29 | DIPPER - Welding and steelwork for cracks and damages | A - Pass |
| 30 | DIPPER - Pins and bushes on hydraulic cylinders | A - Pass |
| 31 | DIPPER - Check valve on dipper cylinder | A - Pass |
| 32 | BUCKET LINKAGE AND QUICK HITCH - Linkage pins and bushes | A - Pass |
| 33 | BUCKET LINKAGE AND QUICK HITCH - Quick hitch condition | A - Pass |
| 34 | BUCKET LINKAGE AND QUICK HITCH - Hook or eye condition | A - Pass |
| 35 | BUCKET LINKAGE AND QUICK HITCH - Hydraulic hoses and pipe work condition | A - Pass |
| 36 | BUCKET LINKAGE AND QUICK HITCH - Check valve is fitted | D - N/A |
| 37 | BUCKET LINKAGE AND QUICK HITCH - Hitch alarm for open position function | A - Pass |
| 38 | Lifting Point | EYE |
| 39 | OPERATOR CABIN - Operator seat | A - Pass |
| 40 | OPERATOR CABIN - Instruments | A - Pass |
| 41 | OPERATOR CABIN - Engine start and stop | A - Pass |
| 42 | OPERATOR CABIN - Control functions lever etc | A - Pass |
| 43 | OPERATOR CABIN - Horn | A - Pass |
| 44 | OPERATOR CABIN - Beacon light | A - Pass |
| 45 | OPERATOR CABIN - Glass / windows | A - Pass |
| 46 | OPERATOR CABIN - Safe access/ step | A - Pass |
| 47 | OPERATOR CABIN - SLI/ RCI (Ref Regulation 55) | A - Pass |
| 48 | OPERATOR CABIN - Load charts in cabin | A - Pass |
| 49 | Is SLI/RCI fitted as per Regulations 55H? | YES |
| 50 | OPERATOR CABIN - Operator all round vision as per Schedule 6 of construction Regulation 2006 Meter Test Results Movement Alarm | A - Pass |
| 51 | FUNCTIONAL CHECKS - Does all control levers operate correctly | A - Pass |
| 52 | FUNCTIONAL CHECKS - Is deadman lever functional properly | A - Pass |
| 53 | FUNCTIONAL CHECKS - Are check valves locking out | A - Pass |
| 54 | FUNCTIONAL CHECKS - Is eye or hook suitable for load test weights | A - Pass |



Unit 11 Crag Crescent, D22 YY48, Ireland T +351 1 457 0021 hoistech.ie



The lifting specialists.

| 55 | FUNCTIONAL CHECKS - Is boom holding (not dropping when left idle) | A - Pass |
|----|--|---|
| 56 | LOAD TEST RESULTS - Safe working load (s) established | A - Pass |
| 57 | LOAD TEST RESULTS - Proof Load (s) established | D - N/A |
| 58 | LOAD TEST RESULTS - Proof load weight test results | D - N/A |
| 59 | LOAD TEST RESULTS - Is HT sticker applied to operator side of boom | A - Pass |
| 60 | LOAD TEST RESULTS - Is machine acceptable for certification | A - Pass |
| 61 | LOAD TEST RESULTS - Hitch alarm for open position function | A - Pass |
| 62 | Boom Length (Mtr) | 3.2 mtr |
| 63 | Dipper Length (Mtr) | 2.3 mtr |
| 64 | SWL (Tonne) | 830kgs |
| 65 | Other Comments | We recommend a preventative maintenance to be carried out |
| 66 | Is this asset safe for use? | SAFE |

We Certify that:

- We have undertaken the test / thorough examination as prescribed
- We have undertaken to identify any defects which are or could be a danger to persons
- This test/thorough examination has been carried out by a competent person
- The particulars in this report of thorough examination are correct

You must:

- Keep this report of thorough examination safe and available for inspection
- ✓ Undertake identified repairs
- Arrange for a thorough examination or test before the latest date or as prescribed

Engineer Name: MARK DUNNE

Engineer Signature



