

QUALITY ASSURANCE

DASCO is third party certified (by NSF International Strategic Registrations) to ISO 9001:2015 + AS9100D, "Quality Management System for the Manufacture of Components and Assemblies for Military and Commercial Aircraft."

The inspection facilities, located in Torrance and Long Beach, CA locations, are enclosed in temperature/humidity controlled rooms, and all inspection and test equipment is calibrated to standards traceable to The National Institute of Standards and Technology (N.I.S.T.)

DASCO's Inspection departments are supported by multiple Mitutoyo, high-speed, 5-axis Coordinate Measuring Machines (CMM's), and a variety of portable inspection arms and laser inspection systems for inspection, measurement or reverse engineering on the shop floor.

